






2DH5_Ant1_2402_30~3000




2DH5_Ant1_2402_2000~26500




Date: 19.FEB.2023 02:33:40

2DH5_Ant1_2441_30~3000




Date: 19.FEB.2023 02:33:06


2DH5_Ant1_2441_2000~26500




2DH5_Ant1_2480_30~3000




2DH5_Ant1_2480_2000~26500



3DH5_Ant1_2402_30~3000




3DH5_Ant1_2402_2000~26500




Date: 19.FEB.2023 02:26:02

3DH5_Ant1_2441_30~3000




Date: 19.FEB.2023 02:27:06

3DH5_Ant1_2441_2000~26500



Date: 19.FEB.2023 02:29:07

3DH5_Ant1_2480_30~3000



Date: 19.FEB.2023 02:28:24

3DH5_Ant1_2480_2000~26500




DUTY CYCLE

TEST RESULT


TestMode	Antenna	Channel	ON Time [ms]	Period [ms]	X	DC [%]	xFactor	Limit	Verdict
DH5	Ant1	2441	2.90	3.76	0.7712	77.13	1.13	---	PASS
2DH5	Ant1	2441	2.87	3.75	0.7653	76.53	1.16	---	PASS
3DH5	Ant1	2441	2.89	3.75	0.7707	77.07	1.13	---	PASS




TEST GRAPHS



DH5_Ant1_2441



2DH5_Ant1_2441



---END---