










Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity


Band41_15MHz_16QAM_40620_1RB#0_0.15~3
0_0.15~30Band41_15MHz_16QAM_40620_1RB#0_30~1000
_30~1000Band41_15MHz_16QAM_40620_1RB#0_1000~2
0000_1000~20000Band41_15MHz_16QAM_40620_1RB#0_20000~2
7000_20000~27000Band41_15MHz_QPSK_41515_1RB#0_0.009~0.
15_0.009~0.15Band41_15MHz_QPSK_41515_1RB#0_0.15~30
0.15~30

Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity




Band41_15MHz_QPSK_41515_1RB#0_30~1000_30~1000




Band41_15MHz_QPSK_41515_1RB#0_1000~20000_1000~20000




Band41_15MHz_QPSK_41515_1RB#0_20000~27000_20000~27000



Band41_15MHz_16QAM_41515_1RB#0_0.009~0.15_0.009~0.15



Band41_15MHz_16QAM_41515_1RB#0_0.15~30_0.15~30



Band41_15MHz_16QAM_41515_1RB#0_30~1000_30~1000




Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity





Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China


Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity







Band41_20MHz_QPSK_40620_1RB#0_0.009~0.15_0.009~0.15




Band41_20MHz_QPSK_40620_1RB#0_0.15~30_0.15~30




Band41_20MHz_QPSK_40620_1RB#0_30~1000_30~1000



Band41_20MHz_QPSK_40620_1RB#0_1000~2000_1000~2000









Band41_20MHz_QPSK_40620_1RB#0_20000~27000_20000~27000



Band41_20MHz_16QAM_40620_1RB#0_0.009~0.15_0.009~0.15



Band41_20MHz_16QAM_40620_1RB#0_0.15~30
0_0.15~30Band41_20MHz_16QAM_40620_1RB#0_30~1000
_30~1000Band41_20MHz_16QAM_40620_1RB#0_1000~2
0000_1000~20000Band41_20MHz_16QAM_40620_1RB#0_2000~2
7000_20000~27000Band41_20MHz_QPSK_41490_1RB#0_0.009~0.
15_0.009~0.15Band41_20MHz_QPSK_41490_1RB#0_0.15~30
0.15~30