



BRANCHPOINT
TECHNOLOGIES

11SEP2018

Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046

Attn: Equipment Authorization Branch
Re: CLASS II PERMISSIVE CHANGE
FCC ID: 2AJW602

Branchpoint Technologies, Inc. hereby requests a Class II Permissive Change as established in 47CFR 2.1043 for the currently-approved FCC ID: 2AJW602. The Class II Permissive Change addresses RF Exposure due to the co-transmission of this RF module with another transmitter when integrated in the AURA™ Monitor Antenna host device. The change is the result of integrating this RF module in the host system with another transmitter. No changes were made to the RF module radio, transmitter, or software.

The enclosed RF Exposure report demonstrates RF Exposure compliance for the two co-transmitting transmitters. This RF Exposure testing and reporting was executed per guidance from the FCC. Reference the enclosed, confidential Operational Description for the relevant KDB inquiry number.

In this host implementation, the RF module is maintained at greater than 5mm from the human body, as specified in the original grant note.

Sincerely,

Kevin Hughes
Chief Technology Officer