

FCC ID change request letter

TUV Rheinland of North America, Inc.
1279 Quarry Lane Suite A
Pleasanton, CA 94566

Date: July 04, 2019

REF: FCC ID, pursuant to section 2.1043, for FCC ID: 2AKCY-HHA19089
IC, pursuant to section RSP-100, for IC: 4706A-HHA19089

Dear Sir or Madam,

Pursuant to section 2.1043, **Cooper Lighting LLC** Hereby submit a request for FCC ID change to our smart bulb, model no.: HHA19609BLE40A, FCC ID: 2AKCY-HHA19609, Grant date: 2019-06-12.

Pursuant to section RSP-100, **Cooper Lighting LLC** Hereby submit a request for IC ID change to our smart bulb, model no.: HHA19609BLE40A, IC: 4706A-HHA19069, Grant date: 2019-06-13.

Original FCC ID	2AKCY-HHA19609	Model name: HHA19609BLE40A	Grant: date2019-06-12
New FCC ID	2AKCY-HHA19089	Model name: HHA19089BLE40A	
Original IC	4706A-HHA19069	PMN/HVIN: HHA19609BLE40A	Grant: date2019-06-13
New IC	4706A-HHA19089	PMN/HVIN: HHA19089BLE40A	

Declaration of the change:

HHA190609BLE40A and HHA19089BLE40A have same appearance, PCB, power and frequency range just has different model name and FCC ID, IC ID for different customers.

All original test result continue to be representative and applicable the equipment under the new FCC ID and IC ID, the new product version is identical to the certified product.

The following documents from the original application remain unchanged, applicable and representative after FCC ID and IC ID change:

- Block Diagram
- Schematics and PCB
- Test setup photos
- Internal Photos
- Operation Description

Due to the change of ID change the following exhibit are changed:

- ID Label & Label location
- User Manual (file rename)
- External Photos(file name)

Compliance / Responsibility statements:

-The product remains compliant with all the applicable rules and requirements once performed this FCC ID and IC ID change.

Sincerely,

For and on behalf of: Cooper Lighting LLC

Chad Ruhala
Compliance Manager

