




Photographs – Internal Photo







ATA Testing Technology Service Co., Ltd.

Report No.: ATA161215007F

Page: 2 of 4







ATA Testing Technology Service Co., Ltd.

Report No.: ATA161215007F

Page: 3 of 4




Bluetooth Antenna



ATA Testing Technology Service Co., Ltd.

Report No.: ATA161215007F

Page: 4 of 4



Chip

