


INTERTEK TESTING SERVICES


Internal Photos



FCC ID: 2ALB3AW70
IC: 23665-HS021

INTERTEK TESTING SERVICES



Internal Photos



FCC ID: 2ALB3AW70
IC: 23665-HS021

INTERTEK TESTING SERVICES



Internal Photos



FCC ID: 2ALB3AW70
IC: 23665-HS021



INTERTEK TESTING SERVICES

Internal Photos





INTERTEK TESTING SERVICES

Internal Photos



INTERTEK TESTING SERVICES



Internal Photos



FCC ID: 2ALB3AW70
IC: 23665-HS021

INTERTEK TESTING SERVICES



Internal Photos



FCC ID: 2ALB3AW70
IC: 23665-HS021

INTERTEK TESTING SERVICES



Internal Photos



FCC ID: 2ALB3AW70
IC: 23665-HS021



INTERTEK TESTING SERVICES

Internal Photos



FCC ID: 2ALB3AW70
IC: 23665-HS021

Internal Photos



FCC ID: 2ALB3AW70
IC: 23665-HS021