

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2ALIF-STR01
17-0027
March 13, 2017
ElectroniXIQ
Stinger Model 001

INTERNAL PHOTOGRAPHS




Figure 1. Component Side of PCB

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2ALIF-STR01
17-0027
March 13, 2017
ElectronIXIQ
Stinger Model 001




Figure 2. Solder Side of PCB