







Band66\_1.4MHz\_QPSK\_132322\_1RB#0\_1000~3000\_1000~3000



Band66\_1.4MHz\_QPSK\_132322\_1RB#0\_3000~20000\_3000~20000



Band66\_1.4MHz\_16QAM\_132322\_1RB#0\_0.009~0.15\_0.009~0.15




Band66\_1.4MHz\_16QAM\_132322\_1RB#0\_0.15~30\_0.15~30




FCC ID: 2ALJF40

Report No.: LCSA10263049EF



Band66\_1.4MHz\_16QAM\_132322\_1RB#0\_30~1000\_30~1000




Band66\_1.4MHz\_16QAM\_132322\_1RB#0\_1000~3000\_1000~3000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_1.4MHz\_16QAM\_132322\_1RB#0\_3000~20000\_3000~20000




Band66\_1.4MHz\_QPSK\_132665\_1RB#0\_0.009~0.15\_0.009~0.15




Band66\_1.4MHz\_QPSK\_132665\_1RB#0\_0.15~30\_0.15~30




Band66\_1.4MHz\_QPSK\_132665\_1RB#0\_30~1000\_30~1000




Band66\_1.4MHz\_QPSK\_132665\_1RB#0\_1000~3000\_1000~3000



Band66\_1.4MHz\_QPSK\_132665\_1RB#0\_3000~20000\_3000~20000



Band66\_1.4MHz\_16QAM\_132665\_1RB#0\_0.009~0.15\_0.009~0.15




Band66\_1.4MHz\_16QAM\_132665\_1RB#0\_0.15~30\_0.15~30




FCC ID: 2ALJF40

Report No.: LCSA10263049EF



Band66\_1.4MHz\_16QAM\_132665\_1RB#0\_30~1000\_30~1000




Band66\_1.4MHz\_16QAM\_132665\_1RB#0\_1000~3000\_1000~3000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_1.4MHz\_16QAM\_132665\_1RB#0\_3000~20000\_3000~20000



Band66\_3MHz\_QPSK\_131987\_1RB#0\_0.009~0.15\_0.009~0.15



Band66\_3MHz\_QPSK\_131987\_1RB#0\_0.15~30\_0.15~30




Band66\_3MHz\_QPSK\_131987\_1RB#0\_30~1000\_30~1000




FCC ID: 2ALJF40

Report No.: LCSA10263049EF



Band66\_3MHz\_QPSK\_131987\_1RB#0\_1000~3000\_1000~3000




Band66\_3MHz\_QPSK\_131987\_1RB#0\_3000~20000\_3000~20000




FCC ID: 2ALJF40

Report No.: LCSA10263049EF



Band66\_3MHz\_16QAM\_131987\_1RB#0\_0.009~0.15\_0.009~0.15




Band66\_3MHz\_16QAM\_131987\_1RB#0\_0.15~30\_0.15~30




FCC ID: 2ALJF40

Report No.: LCSA10263049EF



Band66\_3MHz\_16QAM\_131987\_1RB#0\_30~1000\_30~1000




Band66\_3MHz\_16QAM\_131987\_1RB#0\_1000~3000\_1000~3000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_3MHz\_16QAM\_131987\_1RB#0\_3000~20000\_3000~20000



Band66\_3MHz\_QPSK\_132322\_1RB#0\_0.009~0.15\_0.009~0.15



Band66\_3MHz\_QPSK\_132322\_1RB#0\_0.15~30\_0.15~30




Band66\_3MHz\_QPSK\_132322\_1RB#0\_30~1000\_30~1000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_3MHz\_QPSK\_132322\_1RB#0\_1000~3000\_1000~3000



Band66\_3MHz\_QPSK\_132322\_1RB#0\_3000~20000\_3000~20000



Band66\_3MHz\_16QAM\_132322\_1RB#0\_0.009~0.15\_0.009~0.15




Band66\_3MHz\_16QAM\_132322\_1RB#0\_0.15~30\_0.15~30




FCC ID: 2ALJF40

Report No.: LCSA10263049EF



Band66\_3MHz\_16QAM\_132322\_1RB#0\_30~1000\_30~1000




Band66\_3MHz\_16QAM\_132322\_1RB#0\_1000~3000\_1000~3000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF



Band66\_3MHz\_16QAM\_132322\_1RB#0\_3000~20000\_3000~20000




Band66\_3MHz\_QPSK\_132657\_1RB#0\_0.009~0.15\_0.009~0.15






FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_3MHz\_QPSK\_132657\_1RB#0\_1000~3000\_1000~3000



Band66\_3MHz\_QPSK\_132657\_1RB#0\_3000~20000\_3000~20000



Band66\_3MHz\_16QAM\_132657\_1RB#0\_0.009~0.15\_0.009~0.15




Band66\_3MHz\_16QAM\_132657\_1RB#0\_0.15~30\_0.15~30




FCC ID: 2ALJF40

Report No.: LCSA10263049EF



Band66\_3MHz\_16QAM\_132657\_1RB#0\_30~1000\_30~1000




Band66\_3MHz\_16QAM\_132657\_1RB#0\_1000~3000\_1000~3000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF



Band66\_3MHz\_16QAM\_132657\_1RB#0\_3000~20000\_3000~20000




Band66\_5MHz\_QPSK\_131997\_1RB#0\_0.009~0.15\_0.009~0.15






FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_5MHz\_QPSK\_131997\_1RB#0\_1000~3000\_1000~3000



Band66\_5MHz\_QPSK\_131997\_1RB#0\_3000~20000\_3000~20000



Band66\_5MHz\_16QAM\_131997\_1RB#0\_0.009~0.15\_0.009~0.15




Band66\_5MHz\_16QAM\_131997\_1RB#0\_0.15~30\_0.15~30




FCC ID: 2ALJF40

Report No.: LCSA10263049EF



Band66\_5MHz\_16QAM\_131997\_1RB#0\_30~1000\_30~1000




Band66\_5MHz\_16QAM\_131997\_1RB#0\_1000~3000\_1000~3000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_5MHz\_16QAM\_131997\_1RB#0\_3000~20000\_3000~20000



Band66\_5MHz\_QPSK\_132322\_1RB#0\_0.009~0.15\_0.009~0.15



Band66\_5MHz\_QPSK\_132322\_1RB#0\_0.15~30\_0.15~30




Band66\_5MHz\_QPSK\_132322\_1RB#0\_30~1000\_30~1000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_5MHz\_QPSK\_132322\_1RB#0\_1000~3000\_1000~3000



Band66\_5MHz\_QPSK\_132322\_1RB#0\_3000~20000\_3000~20000



Band66\_5MHz\_16QAM\_132322\_1RB#0\_0.009~0.15\_0.009~0.15




Band66\_5MHz\_16QAM\_132322\_1RB#0\_0.15~30\_0.15~30




FCC ID: 2ALJF40

Report No.: LCSA10263049EF



Band66\_5MHz\_16QAM\_132322\_1RB#0\_30~1000\_30~1000




Band66\_5MHz\_16QAM\_132322\_1RB#0\_1000~3000\_1000~3000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF



Band66\_5MHz\_16QAM\_132322\_1RB#0\_3000~20000\_3000~20000




Band66\_5MHz\_QPSK\_132647\_1RB#0\_0.009~0.15\_0.009~0.15






FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_5MHz\_QPSK\_132647\_1RB#0\_1000~3000\_1000~3000



Band66\_5MHz\_QPSK\_132647\_1RB#0\_3000~20000\_3000~20000



Band66\_5MHz\_16QAM\_132647\_1RB#0\_0.009~0.15\_0.009~0.15




Band66\_5MHz\_16QAM\_132647\_1RB#0\_0.15~30\_0.15~30




FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_5MHz\_16QAM\_132647\_1RB#0\_30~1000\_30~1000




Band66\_5MHz\_16QAM\_132647\_1RB#0\_1000~3000\_1000~3000




Band66 5MHz 16QAM 132647 1RB#0 3000~20000 3000~20000



Band66 10MHz QPSK 132022 1RB#0 0.009~0.15 0.009~0.15



Band66\_10MHz\_QPSK\_132022\_1RB#0\_0.15~30\_0.15~30




Band66\_10MHz\_QPSK\_132022\_1RB#0\_30~1000\_30~1000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_10MHz\_QPSK\_132022\_1RB#0\_1000~3000\_1000~3000



Band66\_10MHz\_QPSK\_132022\_1RB#0\_3000~20000\_3000~20000



Band66\_10MHz\_16QAM\_132022\_1RB#0\_0.009~0.15\_0.009~0.15




Band66\_10MHz\_16QAM\_132022\_1RB#0\_0.15~30\_0.15~30




FCC ID: 2ALJF40

Report No.: LCSA10263049EF



Band66\_10MHz\_16QAM\_132022\_1RB#0\_30~1000\_30~1000




Band66\_10MHz\_16QAM\_132022\_1RB#0\_1000~3000\_1000~3000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_10MHz\_16QAM\_132022\_1RB#0\_3000~20000\_3000~20000



Band66\_10MHz\_QPSK\_132322\_1RB#0\_0.009~0.15\_0.009~0.15



Band66\_10MHz\_QPSK\_132322\_1RB#0\_0.15~30\_0.15~30




Band66\_10MHz\_QPSK\_132322\_1RB#0\_30~1000\_30~1000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_10MHz\_QPSK\_132322\_1RB#0\_1000~3000\_1000~3000



Band66\_10MHz\_QPSK\_132322\_1RB#0\_3000~20000\_3000~20000



Band66\_10MHz\_16QAM\_132322\_1RB#0\_0.009~0.15\_0.009~0.15




Band66\_10MHz\_16QAM\_132322\_1RB#0\_0.15~30\_0.15~30




FCC ID: 2ALJF40

Report No.: LCSA10263049EF



Band66\_10MHz\_16QAM\_132322\_1RB#0\_30~1000\_30~1000




Band66\_10MHz\_16QAM\_132322\_1RB#0\_1000~3000\_1000~3000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_10MHz\_16QAM\_132322\_1RB#0\_3000~20000\_3000~20000




Band66\_10MHz\_QPSK\_132622\_1RB#0\_0.009~0.15\_0.009~0.15




Band66\_10MHz\_QPSK\_132622\_1RB#0\_0.15~30\_0.15~30




Band66\_10MHz\_QPSK\_132622\_1RB#0\_30~1000\_30~1000




Band66\_10MHz\_QPSK\_132622\_1RB#0\_1000~3000\_1000~3000



Band66\_10MHz\_QPSK\_132622\_1RB#0\_3000~20000\_3000~20000



Band66\_10MHz\_16QAM\_132622\_1RB#0\_0.009~0.15\_0.009~0.15




Band66\_10MHz\_16QAM\_132622\_1RB#0\_0.15~30\_0.15~30




FCC ID: 2ALJF40

Report No.: LCSA10263049EF



Band66\_10MHz\_16QAM\_132622\_1RB#0\_30~1000\_30~1000




Band66\_10MHz\_16QAM\_132622\_1RB#0\_1000~3000\_1000~3000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_10MHz\_16QAM\_132622\_1RB#0\_3000~20000\_3000~20000



Band66\_15MHz\_QPSK\_132047\_1RB#0\_0.009~0.15\_0.009~0.15



Band66\_15MHz\_QPSK\_132047\_1RB#0\_0.15~30\_0.15~30




Band66\_15MHz\_QPSK\_132047\_1RB#0\_30~1000\_30~1000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_15MHz\_QPSK\_132047\_1RB#0\_1000~3000\_1000~3000



Band66\_15MHz\_QPSK\_132047\_1RB#0\_3000~20000\_3000~20000



Band66\_15MHz\_16QAM\_132047\_1RB#0\_0.009~0.15\_0.009~0.15




Band66\_15MHz\_16QAM\_132047\_1RB#0\_0.15~30\_0.15~30




FCC ID: 2ALJF40

Report No.: LCSA10263049EF



Band66\_15MHz\_16QAM\_132047\_1RB#0\_30~1000\_30~1000




Band66\_15MHz\_16QAM\_132047\_1RB#0\_1000~3000\_1000~3000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_15MHz\_16QAM\_132047\_1RB#0\_3000~20000\_3000~20000



Band66\_15MHz\_QPSK\_132322\_1RB#0\_0.009~0.15\_0.009~0.15



Band66\_15MHz\_QPSK\_132322\_1RB#0\_0.15~30\_0.15~30




Band66\_15MHz\_QPSK\_132322\_1RB#0\_30~1000\_30~1000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_15MHz\_QPSK\_132322\_1RB#0\_1000~3000\_1000~3000



Band66\_15MHz\_QPSK\_132322\_1RB#0\_3000~20000\_3000~20000



Band66\_15MHz\_16QAM\_132322\_1RB#0\_0.009~0.15\_0.009~0.15




Band66\_15MHz\_16QAM\_132322\_1RB#0\_0.15~30\_0.15~30




FCC ID: 2ALJF40

Report No.: LCSA10263049EF



Band66\_15MHz\_16QAM\_132322\_1RB#0\_30~1000\_30~1000




Band66\_15MHz\_16QAM\_132322\_1RB#0\_1000~3000\_1000~3000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_15MHz\_16QAM\_132322\_1RB#0\_3000~20000\_3000~20000



Band66\_15MHz\_QPSK\_132597\_1RB#0\_0.009~0.15\_0.009~0.15



Band66\_15MHz\_QPSK\_132597\_1RB#0\_0.15~30\_0.15~30




Band66\_15MHz\_QPSK\_132597\_1RB#0\_30~1000\_30~1000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_15MHz\_QPSK\_132597\_1RB#0\_1000~3000\_1000~3000



Band66\_15MHz\_QPSK\_132597\_1RB#0\_3000~20000\_3000~20000



Band66\_15MHz\_16QAM\_132597\_1RB#0\_0.009~0.15\_0.009~0.15




Band66\_15MHz\_16QAM\_132597\_1RB#0\_0.15~30\_0.15~30




FCC ID: 2ALJF40

Report No.: LCSA10263049EF



Band66\_15MHz\_16QAM\_132597\_1RB#0\_30~1000\_30~1000




Band66\_15MHz\_16QAM\_132597\_1RB#0\_1000~3000\_1000~3000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_15MHz\_16QAM\_132597\_1RB#0\_3000~20000\_3000~20000



Band66\_20MHz\_QPSK\_132072\_1RB#0\_0.009~0.15\_0.009~0.15



Band66\_20MHz\_QPSK\_132072\_1RB#0\_0.15~30\_0.15~30




Band66\_20MHz\_QPSK\_132072\_1RB#0\_30~1000\_30~1000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_20MHz\_QPSK\_132072\_1RB#0\_1000~3000\_1000~3000



Band66\_20MHz\_QPSK\_132072\_1RB#0\_3000~20000\_3000~20000



Band66\_20MHz\_16QAM\_132072\_1RB#0\_0.009~0.15\_0.009~0.15




Band66\_20MHz\_16QAM\_132072\_1RB#0\_0.15~30\_0.15~30




FCC ID: 2ALJF40

Report No.: LCSA10263049EF



Band66\_20MHz\_16QAM\_132072\_1RB#0\_30~1000\_30~1000




Band66\_20MHz\_16QAM\_132072\_1RB#0\_1000~3000\_1000~3000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF



Band66\_20MHz\_16QAM\_132072\_1RB#0\_3000~20000\_3000~20000




Band66\_20MHz\_QPSK\_132322\_1RB#0\_0.009~0.15\_0.009~0.15






FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_20MHz\_QPSK\_132322\_1RB#0\_1000~3000\_1000~3000




Band66\_20MHz\_QPSK\_132322\_1RB#0\_3000~20000\_3000~20000




Band66\_20MHz\_16QAM\_132322\_1RB#0\_0.009~0.15\_0.009~0.15



Band66\_20MHz\_16QAM\_132322\_1RB#0\_0.15~30\_0.15~30



Band66\_20MHz\_16QAM\_132322\_1RB#0\_30~1000\_30~1000




Band66\_20MHz\_16QAM\_132322\_1RB#0\_1000~3000\_1000~3000




FCC ID: 2ALJF40


Report No.: LCSA10263049EF




Band66\_20MHz\_16QAM\_132322\_1RB#0\_3000~20000\_3000~20000




Band66\_20MHz\_QPSK\_132572\_1RB#0\_0.009~0.15\_0.009~0.15




Band66\_20MHz\_QPSK\_132572\_1RB#0\_0.15~30\_0.15~30




Band66\_20MHz\_QPSK\_132572\_1RB#0\_30~1000\_30~1000




Band66\_20MHz\_QPSK\_132572\_1RB#0\_1000~3000\_1000~3000



Band66\_20MHz\_QPSK\_132572\_1RB#0\_3000~20000\_3000~20000



Band66\_20MHz\_16QAM\_132572\_1RB#0\_0.009~0.15\_0.009~0.15




Band66\_20MHz\_16QAM\_132572\_1RB#0\_0.15~30\_0.15~30




FCC ID: 2ALJF40

Report No.: LCSA10263049EF



Band66\_20MHz\_16QAM\_132572\_1RB#0\_30~1000\_30~1000



Band66\_20MHz\_16QAM\_132572\_1RB#0\_1000~3000\_1000~3000



FCC ID: 2ALJF40

Report No.: LCSA10263049EF

