



Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 5.SEP.2022 10:45:52

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 5.SEP.2022 10:46:10

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 5.SEP.2022 10:47:46

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 5.SEP.2022 10:48:08

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 5.SEP.2022 10:48:37

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 5.SEP.2022 10:49:08

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 5.SEP.2022 10:49:34

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 5.SEP.2022 10:49:56

Band 4_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 5.SEP.2022 10:50:29

Band 4_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 5.SEP.2022 10:50:54

Band 4_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 5.SEP.2022 10:51:25

Band 4_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 5.SEP.2022 10:51:44

Band 4_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 5.SEP.2022 10:52:12

Band 4_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 5.SEP.2022 10:52:40

Band 4_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 5.SEP.2022 10:54:20

Band 4_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 5.SEP.2022 10:54:49

Band 4_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 5.SEP.2022 10:55:16

Band 4_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 5.SEP.2022 10:55:41

Band 4_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 5.SEP.2022 10:56:15

Band 4_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 5.SEP.2022 10:56:44

Band 4_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 5.SEP.2022 10:57:59

Band 4_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 5.SEP.2022 10:58:24

Band 4_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 5.SEP.2022 10:58:55

Band 4_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 5.SEP.2022 10:59:17

Band 4_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 5.SEP.2022 10:59:48

Band 4_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 5.SEP.2022 11:00:10

Band 4_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:01:33

Band 4_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 5.SEP.2022 11:01:55

Band 4_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:02:23

Band 4_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 5.SEP.2022 11:02:49

Band 4_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:03:17

Band 4_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 5.SEP.2022 11:03:45

Band 4_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:05:58

Band 4_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 5.SEP.2022 11:06:23

Band 4_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:06:46

Band 4_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 5.SEP.2022 11:07:11

Band 4_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:07:43

Band 4_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 5.SEP.2022 11:08:11

Band 4_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:09:44

Band 4_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 5.SEP.2022 11:10:03

Band 4_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:10:35

Band 4_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 5.SEP.2022 11:11:00

Band 4_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 5.SEP.2022 11:11:32

Band 4_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)



Date: 5.SEP.2022 11:11:57