



Band 7_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:12:31

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 5.SEP.2022 11:12:56

Band 7_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:13:27

Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 5.SEP.2022 11:13:52

Band 7_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:14:17

Band 7_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 5.SEP.2022 11:14:45

Band 7_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:15:31

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 5.SEP.2022 11:15:50

Band 7_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:16:15

Band 7_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 5.SEP.2022 11:16:40

Band 7_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:17:08

Band 7_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 5.SEP.2022 11:17:34

Band 7_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:20:07

Band 7_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 5.SEP.2022 11:20:35

Band 7_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:21:04

Band 7_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 5.SEP.2022 11:21:32

Band 7_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:22:01

Band 7_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 5.SEP.2022 11:22:29

Band 7_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:23:35

Band 7_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 5.SEP.2022 11:23:57

Band 7_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:24:26

Band 7_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 5.SEP.2022 11:24:48

Band 7_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:25:18

Band 7_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 5.SEP.2022 11:25:40

Band 12_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:30:30

Band 12_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 5.SEP.2022 11:30:55

Band 12_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:31:23

Band 12_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 5.SEP.2022 11:31:45

Band 12_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:32:16

Band 12_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 5.SEP.2022 11:32:38

Band 12_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:33:59

Band 12_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 5.SEP.2022 11:34:21

Band 12_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:34:49

Band 12_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 5.SEP.2022 11:35:14

Band 12_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:35:45

Band 12_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 5.SEP.2022 11:36:13

Band 12_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:37:33

Band 12_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 5.SEP.2022 11:37:58

Band 12_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:38:26

Band 12_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 5.SEP.2022 11:38:51

Band 12_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:39:22

Band 12_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 5.SEP.2022 11:39:44

Band 12_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)



Date: 5.SEP.2022 11:42:08

Band 12_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)



Date: 5.SEP.2022 11:42:33