



Band 12_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:43:01

Band 12_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 5.SEP.2022 11:43:30

Band 12_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:43:58

Band 12_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 5.SEP.2022 11:44:20

Band 17_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:44:47

Band 17_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 5.SEP.2022 11:45:09

Band 17_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:45:31

Band 17_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 5.SEP.2022 11:45:50

Band 17_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:46:14

Band 17_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 5.SEP.2022 11:46:43

Band 17_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:48:20

Band 17_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 5.SEP.2022 11:48:42

Band 17_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:49:14

Band 17_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 5.SEP.2022 11:49:39

Band 17_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:50:07

Band 17_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 5.SEP.2022 11:50:32

Band 66_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:51:02

Band 66_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 5.SEP.2022 11:51:30

Band 66_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:52:01

Band 66_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 5.SEP.2022 11:52:20

Band 66_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:52:47

Band 66_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 5.SEP.2022 11:53:16

Band 66_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:54:10

Band 66_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 5.SEP.2022 11:54:41

Band 66_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:55:12

Band 66_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 5.SEP.2022 11:55:34

Band 66_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:56:02

Band 66_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 5.SEP.2022 11:56:37

Band 66_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:58:09

Band 66_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 5.SEP.2022 11:58:37

Band 66_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:59:02

Band 66_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 5.SEP.2022 11:59:27

Band 66_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 5.SEP.2022 11:59:58

Band 66_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 5.SEP.2022 12:00:23

Band 66_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 5.SEP.2022 12:02:23

Band 66_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 5.SEP.2022 12:02:45

Band 66_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 5.SEP.2022 12:03:17

Band 66_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 5.SEP.2022 12:03:36

Band 66_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 5.SEP.2022 12:04:04

Band 66_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 5.SEP.2022 12:04:29

Band 66_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 5.SEP.2022 12:09:21

Band 66_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 5.SEP.2022 12:09:53

Band 66_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)



Date: 5.SEP.2022 12:10:18

Band 66_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)



Date: 5.SEP.2022 12:10:53