



## Band 66\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 5.SEP.2022 12:11:25

## Band 66\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 5.SEP.2022 12:11:56

## Band 66\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 5.SEP.2022 12:15:24

## Band 66\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 5.SEP.2022 12:15:53

## Band 66\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 5.SEP.2022 12:16:22

## Band 66\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 5.SEP.2022 12:16:44

## Band 66\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 5.SEP.2022 12:17:09

## Band 66\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 5.SEP.2022 12:17:35

## Band 41\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 14.SEP.2022 19:24:26

## Band 41\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 14.SEP.2022 19:24:51

## Band 41\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 14.SEP.2022 19:25:19

## Band 41\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 14.SEP.2022 19:25:48

## Band 41\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 14.SEP.2022 19:26:10

## Band 41\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 14.SEP.2022 19:26:35

## Band 41\_5 MHz\_High\_QPSK\_RB25#0\_3(26.5GHz-27GHz)




Date: 15.NOV.2022 09:59:47

## Band 41\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 14.SEP.2022 19:27:03

## Band 41\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 14.SEP.2022 19:27:29

## Band 41\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 14.SEP.2022 19:27:51

## Band 41\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 14.SEP.2022 19:28:13

## Band 41\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 14.SEP.2022 19:28:41

## Band 41\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 14.SEP.2022 19:29:07

## Band 41\_10 MHz\_High\_QPSK\_RB50#0\_3(26GHz-27GHz)




Date: 15.NOV.2022 09:59:23

## Band 41\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 14.SEP.2022 19:29:38

## Band 41\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 14.SEP.2022 19:30:07

## Band 41\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 14.SEP.2022 19:30:39

## Band 41\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 14.SEP.2022 19:31:07

## Band 41\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 14.SEP.2022 19:31:33

## Band 41\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 14.SEP.2022 19:31:55

## Band 41\_15 MHz\_High\_QPSK\_RB75#0\_3(26.5GHz-27GHz)




Date: 15.NOV.2022 09:58:53

## Band 41\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 14.SEP.2022 19:32:33

## Band 41\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 14.SEP.2022 19:32:56

## Band 41\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 14.SEP.2022 19:33:28

## Band 41\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 14.SEP.2022 19:33:50

## Band 41\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 14.SEP.2022 19:34:25

## Band 41\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)



Date: 14.SEP.2022 19:34:47

## Band 41\_20 MHz\_High\_QPSK\_RB100#0\_3(26.5GHz-27GHz)



Date: 15.NOV.2022 09:58:25