







11AC20MIMO_Ant1_5785



11AC20MIMO_Ant2_5785




11AC20MIMO_Ant1_5825




Date: 26.AUG.2023 16:29:06

11AC20MIMO_Ant2_5825




Date: 26.AUG.2023 16:30:53

11AC40MIMO_Ant1_5190




Date: 3.SEP.2023 08:25:06


11AC40MIMO_Ant2_5190




11AC40MIMO_Ant1_5230




11AC40MIMO_Ant2_5230




11AC40MIMO_Ant1_5270




11AC40MIMO_Ant2_5270




11AC40MIMO_Ant1_5310




11AC40MIMO_Ant2_5310




11AC40MIMO_Ant1_5510




11AC40MIMO_Ant2_5510




11AC40MIMO_Ant1_5550




11AC40MIMO_Ant2_5550




11AC40MIMO_Ant1_5670




11AC40MIMO_Ant2_5670




11AC40MIMO_Ant1_5710



11AC40MIMO_Ant2_5710




11AC40MIMO_Ant1_5755




Date: 26.AUG.2023 16:33:52

11AC40MIMO_Ant2_5755




Date: 26.AUG.2023 16:35:39

11AC40MIMO_Ant1_5795




Date: 26.AUG.2023 16:38:15


11AC40MIMO_Ant2_5795




11AC80MIMO_Ant1_5210



11AC80MIMO_Ant2_5210




11AC80MIMO_Ant1_5290




Date: 2.SEP.2023 22:10:05

11AC80MIMO_Ant2_5290




Date: 2.SEP.2023 22:12:03

11AC80MIMO_Ant1_5530




Date: 2.SEP.2023 22:15:35

11AC80MIMO_Ant2_5530




Date: 2.SEP.2023 22:17:32

11AC80MIMO_Ant1_5610




Date: 2.SEP.2023 22:21:58

11AC80MIMO_Ant2_5610




Date: 2.SEP.2023 22:23:55


11AC80MIMO_Ant1_5690




11AC80MIMO_Ant2_5690



11AC80MIMO_Ant1_5775



11AC80MIMO_Ant2_5775



-----End of the report-----