



October 11, 2017

Timco
Applications Reviewer

Subject: RE: TIMCO-TCB/Request for additional info - SANITAG
TECHNOLOGIES CORPORATION - FCC ID: 2AMOW-AT004H - JOB #:
1752BUC17

Per your suggestion, we are requesting that FCC Certification for the above referenced project be dismissed and re-issued because the original DXX Form 731 for this project was not marked for a composite filing and the product contains a UWB Device which requires a PAG before issuance of the certificate.

We are:

1. Requesting use of FCC ID: 2AMOW-AT004H for both the UWB and DXX portions of the device.
2. Declaring that the device has not been and will not be sold since the UWB certificate is still pending.
3. Stating that Form 731 will be corrected to indicate that this is a composite filing and re-filed for the DXX device along with the separate UWB application currently pending.
4. We understand that a PAG will be submitted for the UWB before the device is granted.

Best Regards,

Doga Soyler
Sanitag