

July. 24 , 2023

Attestation for signal booster: FCC

ID: 2AMPB-18P5LLCPA1

Each Signal Booster certificated under FCC ID: 2AMPB-18P5LLCPA1 is manufactured

and individually tested to ensure FCC compliance:

- (1) Licensee consent for Fixed consumer booster has been obtained (consent be made available upon FCC/ TCB request)
- (2) NPS and other compliance/ safeguard features have been implemented
- (3) NPS and other compliance/ safeguard features are defaulted to “ ON” configuration (in operation)
- (4) NPS and other compliance/ safeguard features cannot be field reconfigured, disabled or removed
- (5) This Consumer booster is not user programmable, does not need fine tuning or adjustment, does not require professional installation .
- (6) Future software upgrade will not cause non- compliance.

Yours sincerely,

Peter Shi

A handwritten signature in black ink that reads "Peter Shi". The signature is written in a cursive, flowing style.