



Test report No. : 4788402176A-US-R1-V0
Issued date : Apr. 13, 2018
FCC ID : 2AMPP-FB00000

10. Radiated Measurement Setup Configuration

1-18 GHz Front



1-18 GHz Back



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0876 / 1.1



Test report No. : 4788402176A-US-R1-V0
Issued date : Apr. 13, 2018
FCC ID : 2AMPP-FB00000

18-25 GHz Front



18-25 GHz Back



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000

Facsimile (FAX) :+886-3-583-7948

Doc No: 17-EM-F0876 / 1.1



Test report No. : 4788402176A-US-R1-V0
Issued date : Apr. 13, 2018
FCC ID : 2AMPP-FB00000

30-1000 MHz Front



30-1000 MHz Back



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000

Facsimile (FAX) :+886-3-583-7948

Doc No: 17-EM-F0876 / 1.1



Test report No. : 4788402176A-US-R1-V0


Issued date : Apr. 13, 2018

FCC ID : 2AMPP-FB00000

9 kHz-30 MHz Front



9 kHz-30 MHz Back



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000

Facsimile (FAX) :+886-3-583-7948

Doc No: 17-EM-F0876 / 1.1



Test report No. : 4788402176A-US-R1-V0

Issued date : Apr. 13, 2018

FCC ID : 2AMPP-FB00000

11. Conducted Emission Measurement Setup Configurations



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000

Facsimile (FAX) :+886-3-583-7948

Doc No: 17-EM-F0876 / 1.1