





Band edge measurements











11N40SISO-Ant1-2422-PASS



11N40SISO-Ant1-2452-PASS

Emission level measurement








11B-Ant1-2412-1000~26500-PASS





11B-Ant1-2437-0~Reference-PASS















11G-Ant1-2437-1000~26500-PASS



11G-Ant1-2462-0~Reference-PASS

