



5MHz_Low_QPSK_1@0




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 14.FEB.2025 12:40:28

5MHz_Low_QPSK_25@0




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 14.FEB.2025 12:40:53

5MHz_Low_16QAM_1@0




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 14.FEB.2025 12:41:18

5MHz_Low_16QAM_25@0




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 14.FEB.2025 12:41:43

5MHz_High_QPSK_1@24




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 14.FEB.2025 12:42:17

5MHz_High_QPSK_25@0




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 14.FEB.2025 12:42:42

5MHz_High_16QAM_1@24




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 14.FEB.2025 12:43:07

5MHz_High_16QAM_25@0




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 14.FEB.2025 12:43:32

10MHz_Low_QPSK_1@0




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 14.FEB.2025 12:44:19

10MHz_Low_QPSK_50@0




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 14.FEB.2025 12:44:55

10MHz_Low_16QAM_1@0




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 14.FEB.2025 12:45:30

10MHz_Low_16QAM_25@0




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 14.FEB.2025 12:46:05

10MHz_High_QPSK_1@49




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 14.FEB.2025 12:46:50

10MHz_High_QPSK_50@0




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 14.FEB.2025 12:47:26

10MHz_High_16QAM_1@49




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 14.FEB.2025 12:48:01

10MHz_High_16QAM_25@25




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 14.FEB.2025 12:48:36

15MHz_Low_QPSK_1@0




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 14.FEB.2025 12:49:33

15MHz_Low_QPSK_75@0




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 14.FEB.2025 12:50:17

15MHz_Low_16QAM_1@0




ProjectNo.:2502P26774E-RF Tester:Loge Long
 Date: 14.FEB.2025 12:51:01

15MHz_Low_16QAM_25@0




ProjectNo.:2502P26774E-RF Tester:Loge Long
 Date: 14.FEB.2025 12:51:45

15MHz_High_QPSK_1@74




ProjectNo.:2502P26774E-RF Tester:Loge Long
 Date: 14.FEB.2025 12:52:37

15MHz_High_QPSK_75@0




ProjectNo.:2502P26774E-RF Tester:Loge Long
 Date: 14.FEB.2025 12:53:20

15MHz_High_16QAM_1@74



ProjectNo.:2502P26774E-RF Tester:Loge Long
 Date: 14.FEB.2025 12:54:04



15MHz_High_16QAM_25@50



ProjectNo.:2502P26774E-RF Tester:Loge Long
 Date: 14.FEB.2025 12:54:48



20MHz_Low_QPSK_1@0

20MHz_Low_QPSK_100@0





20MHz_Low_16QAM_1@0

20MHz_Low_16QAM_25@0




20MHz_High_QPSK_1@99


20MHz_High_QPSK_100@0



20MHz_High_16QAM_1@99



20MHz_High_16QAM_25@75




Spurious Emissions at Antenna Terminal

FCC Part 22H

Band 5, Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 13.FEB.2025 23:23:04

1.4MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 13.FEB.2025 23:23:27

1.4MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 24.FEB.2025 14:47:20

3MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 13.FEB.2025 23:26:15

3MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 13.FEB.2025 23:26:38

3MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 24.FEB.2025 15:02:08


5MHz_Low_QPSK_1@0(30MHz~9.49GHz)




5MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




5MHz_High_QPSK_1@0(30MHz~9.49GHz)




10MHz_Low_QPSK_1@0(30MHz~9.49GHz)



10MHz_Middle_QPSK_1@0(30MHz~9.49GHz)



10MHz_High_QPSK_1@0(30MHz~9.49GHz)




FCC Part 24E

Band 2, Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 24.FEB.2025 14:37:21

1.4MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 13.FEB.2025 22:39:03

1.4MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 13.FEB.2025 22:39:28

3MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 24.FEB.2025 14:39:49

3MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 13.FEB.2025 22:41:50

3MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 13.FEB.2025 22:42:15


5MHz_Low_QPSK_1@0(30MHz~20.1GHz)




5MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




5MHz_High_QPSK_1@0(30MHz~20.1GHz)




10MHz_Low_QPSK_1@0(30MHz~20.1GHz)




10MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




10MHz_High_QPSK_1@0(30MHz~20.1GHz)




15MHz_Low_QPSK_1@0(30MHz~20.1GHz)




15MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




15MHz_High_QPSK_1@0(30MHz~20.1GHz)




20MHz_Low_QPSK_1@0(30MHz~20.1GHz)



20MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




20MHz_High_QPSK_1@0(30MHz~20.1GHz)




Band 4, Normal
1RB was the worst case


1.4MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




3MHz_Low_QPSK_1@0(30MHz~18.55GHz)




3MHz_High_QPSK_1@0(30MHz~18.55GHz)




5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




5MHz_High_QPSK_1@0(30MHz~18.55GHz)




10MHz_Low_QPSK_1@0(30MHz~18.55GHz)




10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




10MHz_High_QPSK_1@0(30MHz~18.55GHz)




15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




15MHz_High_QPSK_1@0(30MHz~18.55GHz)




20MHz_Low_QPSK_1@0(30MHz~18.55GHz)



20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




20MHz_High_QPSK_1@0(30MHz~18.55GHz)




Band 7, Normal
1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 13.FEB.2025 23:35:05

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 13.FEB.2025 23:35:35

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 24.FEB.2025 14:53:25

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 13.FEB.2025 23:38:21

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 13.FEB.2025 23:39:18

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 13.FEB.2025 23:40:16

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 13.FEB.2025 23:43:20

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 13.FEB.2025 23:44:17

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 13.FEB.2025 23:45:14

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 24.FEB.2025 14:55:39

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 24.FEB.2025 14:56:02


20MHz_High_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 13.FEB.2025 23:49:44


Band 66, Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 13.FEB.2025 23:51:00

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 13.FEB.2025 23:51:26

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 13.FEB.2025 23:51:53

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 13.FEB.2025 23:52:22

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 13.FEB.2025 23:52:49

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
Date: 24.FEB.2025 14:57:32


5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




5MHz_High_QPSK_1@0(30MHz~18.8GHz)




10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



10MHz_High_QPSK_1@0(30MHz~18.8GHz)




15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
 Date: 13.FEB.2025 23:57:31

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
 Date: 13.FEB.2025 23:58:24

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
 Date: 13.FEB.2025 23:59:16

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P26774E-RF Tester:Loge Long
 Date: 14.FEB.2025 00:00:14

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2502P26774E-RF Tester:Loge Long
 Date: 14.FEB.2025 00:01:06

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2502P26774E-RF Tester:Loge Long
 Date: 14.FEB.2025 00:01:57

***** END *****