

The size of the module is too small, so the FCC ID is indicated on the manual and the packaging.