



15MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:23:34

15MHz_Low_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 14.AUG.2026 23:48:13

15MHz_Low_QPSK_1@0(15GHz~25.075GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:23:50

15MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:24:04

15MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:24:11

15MHz_Middle_QPSK_1@0(15GHz~25.35GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:24:19


15MHz_High_QPSK_1@0(30MHz~1GHz)




15MHz_High_QPSK_1@0(1GHz~15GHz)




15MHz_High_QPSK_1@0(15GHz~25.625GHz)




20MHz_Low_QPSK_1@0(30MHz~1GHz)




20MHz_Low_QPSK_1@0(1GHz~15GHz)



20MHz_Low_QPSK_1@0(15GHz~25.1GHz)




20MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:25:31

20MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:25:39

20MHz_Middle_QPSK_1@0(15GHz~25.35GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:25:46

20MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:25:57

20MHz_High_QPSK_1@0(1GHz~15GHz)



ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:26:05

20MHz_High_QPSK_1@0(15GHz~25.6GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:26:12

LTE Band 12, Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:09:01

1.4MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:09:14

1.4MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:09:29

3MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:09:46

3MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:09:57

3MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:10:08

5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:10:21

5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:10:32

5MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:10:43

10MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:10:57

10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:11:10

10MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:11:22

LTE Band 17, Normal


1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:11:50

5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:12:02

5MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:12:15

10MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:12:32

10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:12:44

10MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:12:58

LTE Band 66, Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:13:29

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:13:41

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:13:51

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:14:05

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:14:15

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:14:26


5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




5MHz_High_QPSK_1@0(30MHz~18.8GHz)




10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



10MHz_High_QPSK_1@0(30MHz~18.8GHz)




15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:16:03

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:16:14

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:16:26

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:16:41

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:16:51

20MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 20:17:02


LTE Band 71, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~7.98GHz)




5MHz_Middle_QPSK_1@0(30MHz~7.98GHz)




5MHz_High_QPSK_1@0(30MHz~7.98GHz)




10MHz_Low_QPSK_1@0(30MHz~7.98GHz)




10MHz_Middle_QPSK_1@0(30MHz~7.98GHz)



10MHz_High_QPSK_1@0(30MHz~7.98GHz)




15MHz_Low_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 23:49:57

15MHz_Middle_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 23:50:20

15MHz_High_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 23:50:47

20MHz_Low_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 23:51:09

20MHz_Middle_QPSK_1@0(30MHz~7.98GHz)



ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 23:51:30

20MHz_High_QPSK_1@0(30MHz~7.98GHz)



ProjectNo.:2602V17767E-RF Tester:Loge Long
Date: 12.AUG.2026 23:51:52

***** END *****