

No Gain from 26 to 28 MHz

Drive was applied at 26.01 MHz. Observed gain was 0 dB

Drive was applied at 27.99 Mhz. Observed gain was 0 dB