

Appendix C – SAR Test Setup Photos



Test Position Back 0 mm Gap

Note: AC power cable removed for testing.



Test Position Front 0 mm Gap

Note: AC power cable removed for testing.



Front of Device



Back of Device