






Date: 29.AUG.2019 12:32:00

Band2_5MHz_QPSK_18900_1RB#0




Date: 29.AUG.2019 12:34:03

Band2_5MHz_QPSK_18900_1RB#0




Date: 29.AUG.2019 12:34:12

Band2_5MHz_QPSK_18900_1RB#0




Date: 29.AUG.2019 12:34:24

Band2_5MHz_QPSK_18900_1RB#0




Date: 29.AUG.2019 12:34:51

Band2_5MHz_QPSK_18900_1RB#0




Date: 29.AUG.2019 12:35:17

Band2_5MHz_QPSK_18900_1RB#0




Date: 29.AUG.2019 12:35:43

Band2_5MHz_QPSK_19175_1RB#0




Date: 29.AUG.2019 12:37:45

Band2_5MHz_QPSK_19175_1RB#0




Date: 29.AUG.2019 12:37:54

Band2_5MHz_QPSK_19175_1RB#0




Date: 29.AUG.2019 12:38:06

Band2_5MHz_QPSK_19175_1RB#0




Date: 29.AUG.2019 12:38:33

Band2_5MHz_QPSK_19175_1RB#0




Date: 29.AUG.2019 12:38:58

Band2_5MHz_QPSK_19175_1RB#0




Date: 29.AUG.2019 12:39:24

Band2_5MHz_16QAM_18625_1RB#0




Date: 29.AUG.2019 12:32:11

Band2_5MHz_16QAM_18625_1RB#0




Date: 29.AUG.2019 12:32:20

Band2_5MHz_16QAM_18625_1RB#0




Date: 29.AUG.2019 12:32:31

Band2_5MHz_16QAM_18625_1RB#0




Date: 29.AUG.2019 12:32:58

Band2_5MHz_16QAM_18625_1RB#0




Date: 29.AUG.2019 12:33:24

Band2_5MHz_16QAM_18625_1RB#0




Date: 29.AUG.2019 12:33:58

Band2_5MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 12:35:53

Band2_5MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 12:36:02

Band2_5MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 12:36:14

Band2_5MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 12:36:40

Band2_5MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 12:37:06


Band2_5MHz_16QAM_18900_1RB#0




Band2_5MHz_16QAM_19175_1RB#0



Band2_5MHz_16QAM_19175_1RB#0




Band2_5MHz_16QAM_19175_1RB#0




Date: 29.AUG.2019 12:39:55

Band2_5MHz_16QAM_19175_1RB#0




Date: 29.AUG.2019 12:40:22

Band2_5MHz_16QAM_19175_1RB#0




Date: 29.AUG.2019 12:40:48

Band2_5MHz_16QAM_19175_1RB#0




Date: 29.AUG.2019 12:41:14

Band2_10MHz_QPSK_18650_1RB#0




Date: 29.AUG.2019 12:55:05

Band2_10MHz_QPSK_18650_1RB#0




Date: 29.AUG.2019 12:55:15

Band2_10MHz_QPSK_18650_1RB#0




Date: 29.AUG.2019 12:55:26

Band2_10MHz_QPSK_18650_1RB#0




Date: 29.AUG.2019 12:55:53

Band2_10MHz_QPSK_18650_1RB#0




Date: 29.AUG.2019 12:56:19

Band2_10MHz_QPSK_18650_1RB#0




Date: 29.AUG.2019 12:56:45

Band2_10MHz_QPSK_18900_1RB#0




Date: 29.AUG.2019 12:58:47

Band2_10MHz_QPSK_18900_1RB#0




Date: 29.AUG.2019 12:58:57

Band2_10MHz_QPSK_18900_1RB#0




Date: 29.AUG.2019 12:59:08

Band2_10MHz_QPSK_18900_1RB#0




Date: 29.AUG.2019 12:59:35

Band2_10MHz_QPSK_18900_1RB#0




Date: 29.AUG.2019 13:00:01

Band2_10MHz_QPSK_18900_1RB#0




Date: 29.AUG.2019 13:00:27

Band2_10MHz_QPSK_19150_1RB#0




Date: 29.AUG.2019 13:02:29

Band2_10MHz_QPSK_19150_1RB#0




Date: 29.AUG.2019 13:02:39


Band2_10MHz_QPSK_19150_1RB#0




Band2_10MHz_QPSK_19150_1RB#0



Band2_10MHz_QPSK_19150_1RB#0




Band2_10MHz_QPSK_19150_1RB#0




Date: 29.AUG.2019 13:04:09

Band2_10MHz_16QAM_18650_1RB#0




Date: 29.AUG.2019 12:56:55

Band2_10MHz_16QAM_18650_1RB#0




Date: 29.AUG.2019 12:57:04

Band2_10MHz_16QAM_18650_1RB#0




Date: 29.AUG.2019 12:57:16

Band2_10MHz_16QAM_18650_1RB#0




Date: 29.AUG.2019 12:57:43

Band2_10MHz_16QAM_18650_1RB#0




Date: 29.AUG.2019 12:58:09

Band2_10MHz_16QAM_18650_1RB#0




Date: 29.AUG.2019 12:58:35

Band2_10MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 13:00:37

Band2_10MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 13:00:46

Band2_10MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 13:00:58

Band2_10MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 13:01:25

Band2_10MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 13:01:51

Band2_10MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 13:02:17

Band2_10MHz_16QAM_19150_1RB#0




Date: 29.AUG.2019 13:04:19

Band2_10MHz_16QAM_19150_1RB#0




Date: 29.AUG.2019 13:04:29

Band2_10MHz_16QAM_19150_1RB#0




Date: 29.AUG.2019 13:04:48

Band2_10MHz_16QAM_19150_1RB#0




Date: 29.AUG.2019 13:05:07

Band2_10MHz_16QAM_19150_1RB#0




Date: 29.AUG.2019 13:05:33

Band2_10MHz_16QAM_19150_1RB#0




Date: 29.AUG.2019 13:05:59

Band2_15MHz_QPSK_18675_1RB#0




Date: 29.AUG.2019 13:21:21

Band2_15MHz_QPSK_18675_1RB#0




Date: 29.AUG.2019 13:21:31

Band2_15MHz_QPSK_18675_1RB#0




Date: 29.AUG.2019 13:21:42

Band2_15MHz_QPSK_18675_1RB#0




Date: 29.AUG.2019 13:22:09

Band2_15MHz_QPSK_18675_1RB#0




Date: 29.AUG.2019 13:22:35

Band2_15MHz_QPSK_18675_1RB#0




Date: 29.AUG.2019 13:23:01

Band2_15MHz_QPSK_18900_1RB#0




Date: 29.AUG.2019 13:25:03

Band2_15MHz_QPSK_18900_1RB#0




Date: 29.AUG.2019 13:25:12


Band2_15MHz_QPSK_18900_1RB#0




Band2_15MHz_QPSK_18900_1RB#0



Band2_15MHz_QPSK_18900_1RB#0




Band2_15MHz_QPSK_18900_1RB#0




Date: 29.AUG.2019 13:26:43

Band2_15MHz_QPSK_19125_1RB#0




Date: 29.AUG.2019 13:28:45

Band2_15MHz_QPSK_19125_1RB#0




Date: 29.AUG.2019 13:28:54

Band2_15MHz_QPSK_19125_1RB#0




Date: 29.AUG.2019 13:29:06

Band2_15MHz_QPSK_19125_1RB#0




Date: 29.AUG.2019 13:29:33

Band2_15MHz_QPSK_19125_1RB#0




Date: 29.AUG.2019 13:29:58

Band2_15MHz_QPSK_19125_1RB#0




Date: 29.AUG.2019 13:30:24

Band2_15MHz_16QAM_18675_1RB#0




Date: 29.AUG.2019 13:23:11

Band2_15MHz_16QAM_18675_1RB#0




Date: 29.AUG.2019 13:23:20

Band2_15MHz_16QAM_18675_1RB#0




Date: 29.AUG.2019 13:23:32

Band2_15MHz_16QAM_18675_1RB#0




Date: 29.AUG.2019 13:23:59

Band2_15MHz_16QAM_18675_1RB#0




Date: 29.AUG.2019 13:24:25

Band2_15MHz_16QAM_18675_1RB#0




Date: 29.AUG.2019 13:24:58

Band2_15MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 13:26:53

Band2_15MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 13:27:02

Band2_15MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 13:27:14

Band2_15MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 13:27:41

Band2_15MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 13:28:06

Band2_15MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 13:28:32

Band2_15MHz_16QAM_19125_1RB#0




Date: 29.AUG.2019 13:30:34

Band2_15MHz_16QAM_19125_1RB#0




Date: 29.AUG.2019 13:30:44

Band2_15MHz_16QAM_19125_1RB#0




Date: 29.AUG.2019 13:30:55

Band2_15MHz_16QAM_19125_1RB#0




Date: 29.AUG.2019 13:31:22

Band2_15MHz_16QAM_19125_1RB#0




Date: 29.AUG.2019 13:31:48

Band2_15MHz_16QAM_19125_1RB#0




Date: 29.AUG.2019 13:32:14

Band2_20MHz_QPSK_18700_1RB#0




Date: 29.AUG.2019 13:47:41

Band2_20MHz_QPSK_18700_1RB#0




Date: 29.AUG.2019 13:47:51

Band2_20MHz_QPSK_18700_1RB#0




Date: 29.AUG.2019 13:48:02

Band2_20MHz_QPSK_18700_1RB#0




Date: 29.AUG.2019 13:48:29

Band2_20MHz_QPSK_18700_1RB#0




Date: 29.AUG.2019 13:48:55

Band2_20MHz_QPSK_18700_1RB#0




Date: 29.AUG.2019 13:49:21

Band2_20MHz_QPSK_18900_1RB#0




Date: 29.AUG.2019 13:51:24

Band2_20MHz_QPSK_18900_1RB#0




Date: 29.AUG.2019 13:51:34

Band2_20MHz_QPSK_18900_1RB#0




Date: 29.AUG.2019 13:51:45

Band2_20MHz_QPSK_18900_1RB#0




Date: 29.AUG.2019 13:52:12

Band2_20MHz_QPSK_18900_1RB#0




Date: 29.AUG.2019 13:52:38

Band2_20MHz_QPSK_18900_1RB#0




Date: 29.AUG.2019 13:53:04

Band2_20MHz_QPSK_19100_1RB#0




Date: 29.AUG.2019 13:55:07

Band2_20MHz_QPSK_19100_1RB#0




Date: 29.AUG.2019 13:55:16

Band2_20MHz_QPSK_19100_1RB#0




Date: 29.AUG.2019 13:55:28

Band2_20MHz_QPSK_19100_1RB#0




Date: 29.AUG.2019 13:55:54

Band2_20MHz_QPSK_19100_1RB#0




Date: 29.AUG.2019 13:56:20

Band2_20MHz_QPSK_19100_1RB#0




Date: 29.AUG.2019 13:56:46

Band2_20MHz_16QAM_18700_1RB#0




Date: 29.AUG.2019 13:49:32

Band2_20MHz_16QAM_18700_1RB#0




Date: 29.AUG.2019 13:49:41

Band2_20MHz_16QAM_18700_1RB#0




Date: 29.AUG.2019 13:49:52

Band2_20MHz_16QAM_18700_1RB#0




Date: 29.AUG.2019 13:50:19

Band2_20MHz_16QAM_18700_1RB#0




Date: 29.AUG.2019 13:50:45

Band2_20MHz_16QAM_18700_1RB#0




Date: 29.AUG.2019 13:51:11

Band2_20MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 13:53:14

Band2_20MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 13:53:24

Band2_20MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 13:53:35

Band2_20MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 13:54:02

Band2_20MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 13:54:28

Band2_20MHz_16QAM_18900_1RB#0




Date: 29.AUG.2019 13:54:54

Band2_20MHz_16QAM_19100_1RB#0




Date: 29.AUG.2019 13:56:57

Band2_20MHz_16QAM_19100_1RB#0




Date: 29.AUG.2019 13:57:06

Band2_20MHz_16QAM_19100_1RB#0




Date: 29.AUG.2019 13:57:18

Band2_20MHz_16QAM_19100_1RB#0




Date: 29.AUG.2019 13:57:45

Band2_20MHz_16QAM_19100_1RB#0



Date: 29.AUG.2019 13:58:11

Band2_20MHz_16QAM_19100_1RB#0



Date: 29.AUG.2019 13:58:37

Appendix F: Frequency Stability

Test Result

Voltage										
Band	Bandwidth	Modulation	Channel	RB Configure	Voltage [Vdc]	Temperature (°C)	Deviation (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
Band2	1.4MHz	QPSK	18900	6RB#0	VL	NT	-8.50	-0.004521	±2.5	PASS
Band2	1.4MHz	QPSK	18900	6RB#0	VN	NT	-8.75	-0.004654	±2.5	PASS
Band2	1.4MHz	QPSK	18900	6RB#0	VH	NT	-7.93	-0.004218	±2.5	PASS
Band2	3MHz	QPSK	18900	15RB#0	VL	NT	-6.82	-0.003628	±2.5	PASS
Band2	3MHz	QPSK	18900	15RB#0	VN	NT	-8.50	-0.004521	±2.5	PASS
Band2	3MHz	QPSK	18900	15RB#0	VH	NT	-7.01	-0.003729	±2.5	PASS
Band2	5MHz	QPSK	18900	25RB#0	VL	NT	-10.00	-0.005319	±2.5	PASS
Band2	5MHz	QPSK	18900	25RB#0	VN	NT	-7.28	-0.003872	±2.5	PASS
Band2	5MHz	QPSK	18900	25RB#0	VH	NT	-7.18	-0.003819	±2.5	PASS
Band2	10MHz	QPSK	18900	50RB#0	VL	NT	-6.61	-0.003516	±2.5	PASS
Band2	10MHz	QPSK	18900	50RB#0	VN	NT	-6.95	-0.003697	±2.5	PASS
Band2	10MHz	QPSK	18900	50RB#0	VH	NT	-7.52	-0.004000	±2.5	PASS
Band2	15MHz	QPSK	18900	75RB#0	VL	NT	-7.20	-0.003830	±2.5	PASS
Band2	15MHz	QPSK	18900	75RB#0	VN	NT	-6.48	-0.003447	±2.5	PASS
Band2	15MHz	QPSK	18900	75RB#0	VH	NT	-8.24	-0.004383	±2.5	PASS
Band2	20MHz	QPSK	18900	100RB#0	VL	NT	-7.04	-0.003745	±2.5	PASS
Band2	20MHz	QPSK	18900	100RB#0	VN	NT	-7.65	-0.004069	±2.5	PASS
Band2	20MHz	QPSK	18900	100RB#0	VH	NT	-6.72	-0.003574	±2.5	PASS

Temperature										
Band	Bandwidth	Modulation	Channel	RB Configure	Voltage [Vdc]	Temperature (°C)	Deviation (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
Band2	1.4MHz	QPSK	18900	6RB#0	NV	-30	-8.50	-0.004521	±2.5	PASS
Band2	1.4MHz	QPSK	18900	6RB#0	NV	-20	-7.54	-0.004011	±2.5	PASS
Band2	1.4MHz	QPSK	18900	6RB#0	NV	0	-9.06	-0.004819	±2.5	PASS
Band2	1.4MHz	QPSK	18900	6RB#0	NV	10	-8.45	-0.004495	±2.5	PASS
Band2	1.4MHz	QPSK	18900	6RB#0	NV	20	-8.00	-0.004255	±2.5	PASS
Band2	3MHz	QPSK	18900	15RB#0	NV	-30	-7.07	-0.003761	±2.5	PASS
Band2	3MHz	QPSK	18900	15RB#0	NV	-20	-6.11	-0.003250	±2.5	PASS
Band2	3MHz	QPSK	18900	15RB#0	NV	0	-8.44	-0.004489	±2.5	PASS
Band2	3MHz	QPSK	18900	15RB#0	NV	10	-7.47	-0.003973	±2.5	PASS
Band2	3MHz	QPSK	18900	15RB#0	NV	20	-6.95	-0.003697	±2.5	PASS
Band2	5MHz	QPSK	18900	25RB#0	NV	-30	-6.32	-0.003362	±2.5	PASS
Band2	5MHz	QPSK	18900	25RB#0	NV	-20	-7.11	-0.003782	±2.5	PASS
Band2	5MHz	QPSK	18900	25RB#0	NV	0	-7.11	-0.003782	±2.5	PASS
Band2	5MHz	QPSK	18900	25RB#0	NV	10	-6.98	-0.003713	±2.5	PASS
Band2	5MHz	QPSK	18900	25RB#0	NV	20	-9.37	-0.004984	±2.5	PASS
Band2	10MHz	QPSK	18900	50RB#0	NV	-30	-10.64	-0.005660	±2.5	PASS
Band2	10MHz	QPSK	18900	50RB#0	NV	-20	-9.03	-0.004803	±2.5	PASS
Band2	10MHz	QPSK	18900	50RB#0	NV	0	-6.94	-0.003691	±2.5	PASS
Band2	10MHz	QPSK	18900	50RB#0	NV	10	-6.85	-0.003644	±2.5	PASS
Band2	10MHz	QPSK	18900	50RB#0	NV	20	-5.52	-0.002936	±2.5	PASS

Band2	15MHz	QPSK	18900	75RB#0	NV	-30	-6.74	-0.003585	±2.5	PASS
Band2	15MHz	QPSK	18900	75RB#0	NV	-20	-7.65	-0.004069	±2.5	PASS
Band2	15MHz	QPSK	18900	75RB#0	NV	0	-8.47	-0.004505	±2.5	PASS
Band2	15MHz	QPSK	18900	75RB#0	NV	10	-7.87	-0.004186	±2.5	PASS
Band2	15MHz	QPSK	18900	75RB#0	NV	20	-7.97	-0.004239	±2.5	PASS
Band2	20MHz	QPSK	18900	100RB#0	NV	-30	-6.34	-0.003372	±2.5	PASS
Band2	20MHz	QPSK	18900	100RB#0	NV	-20	-5.75	-0.003059	±2.5	PASS
Band2	20MHz	QPSK	18900	100RB#0	NV	0	-7.85	-0.004176	±2.5	PASS
Band2	20MHz	QPSK	18900	100RB#0	NV	10	-6.64	-0.003532	±2.5	PASS
Band2	20MHz	QPSK	18900	100RB#0	NV	20	-8.45	-0.004495	±2.5	PASS