

175*80mm

MODEL:S9N29R
INPUT 120V~,60Hz, 1050W, 2450MHz
FCC ID: 2ANXA-6733



This device complies with part 15 of the FCC Rules.
Operation is subject to the following two conditions:
(1) This device may not cause harmful interference.
(2) this device must accept any interference received,
including interference that may cause undesired operation.
This device complies with Part 18 of the FCC Rules.

THIS DEVICE COMPLIES WITH DHHS RADIATION PERFORMANCE
STANDARDS 21 CFR SUBCHAPTER J.

MANUFACTURED: MMYYYY
MADE IN CHINA

CAUTION·THIS DEVICE IS TO BE SERVICED ONLY BY
PROPERLY QUALIFIED SERVICE PERSONNEL. CONSULT
THE SERVICE MANUAL FOR PROPER SERVICE PROCEDURES
TO ASSURE CONTINUED COMPLIANCE WITH THE FEDERAL
PERFORMANCE STANDARD FOR MICROWAVE OVENS AND
FOR PRECAUTIONS TO BE TAKEN TO AVOID POSSIBLE
EXPOSURE TO EXCESSIVE MICROWAVE ENERGY.

WARNING·TO PROVIDE CONTINUED PROTECTION AGAINST
ELECTRICAL SHOCK HAZARD, CONNECT TO PROPERLY
GROUNDED OUTLETS ONLY.DISCONNECT APPLIANCE
BEFORE SERVICING. REMOVAL OF OUTERCASE WITH
PRODUCT ENERGIZED MAY EXPOSE SERVICEMAN TO
HAZARDOUS HIGH VOLTAGE POTENTIALS.

· CERTAIN INTERNAL PARTS ARE INTENTIONALLY NOT
GROUNDED AND MAY PRESENT A RISK OF ELECTRIC
SHOCK ONLY DURING SERVICING.SERVICE PERSONNEL
-DO NOT CONTACT THE FOLLOWING PARTS WHILE THE
APPLIANCE IS ENERGIZED: IF PROVIDED FAN MOTOR,
TURNABLE MOTOR, DAMPER MOTOR,L.V.TRANSFORMER
(TOUCH CONTROL TYPE) OR TIMER MOTOR ASSEMBLY
(MECHANICAL TYPE).

· RISK OF ELECTRIC SHOCK. NON-REMOVABLE FASTENERS
ARE PROVIDED BECAUSE OF INTERNAL HIGH VOLTAGES.
DO NOT REMOVE FASTENERS.

· NOT FOR BUILT-IN INSTALLATION.

