





Test report No. : 4788387996A-US-R2-V0  
Page : 1 of 4  
Issued date : May 28, 2018  
FCC ID : 2AO4FM020-1

## 1. Radiated Measurement Setup Configuration

### Z-axis 30-1000MHz Front



### Z-axis 30-1000MHz Back



### Underwriters Laboratories Taiwan Co., Ltd.


Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan  
Telephone : +886-2-7737-3000  
Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0875 / 1.0




Test report No. : 4788387996A-US-R2-V0  
Page : 2 of 4  
Issued date : May 28, 2018  
FCC ID : 2AO4FM020-1

**Z-axis 9kHz-30MHz Front**



**Z-axis 9kHz-30MHz Back**



**Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan  
Telephone : +886-2-7737-3000  
Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0875 / 1.0



Test report No. : 4788387996A-US-R2-V0  
Page : 3 of 4  
Issued date : May 28, 2018  
FCC ID : 2AO4FM020-1

---

## 2. Conducted Emission Measurement Setup Configurations



### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan  
Telephone : +886-2-7737-3000  
Facsimile (FAX ) : +886-3-583-7948

Doc No: 17-EM-F0875 / 1.0



Test report No. : 4788387996A-US-R2-V0  
Page : 4 of 4  
Issued date : May 28, 2018  
FCC ID : 2AO4FM020-1

---



**Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan  
Telephone :+886-2-7737-3000  
Facsimile (FAX ) :+886-3-583-7948

Doc No: 17-EM-F0875 / 1.0