



Please refer to following plots:




Date: 26.OCT.2022 17:10:48




Date: 26.OCT.2022 17:11:05

Band 2_1.4 MHz_Middle_QPSK_RB6#0




Date: 26.OCT.2022 17:11:26


Band 2_1.4 MHz_Middle_16QAM_RB6#0




Date: 26.OCT.2022 17:11:46




Date: 26.OCT.2022 17:12:08




Date: 26.OCT.2022 17:12:25




Date: 26.OCT.2022 17:12:45




Date: 26.OCT.2022 17:13:00




Date: 26.OCT.2022 17:13:15



Date: 26.OCT.2022 17:13:29




Date: 26.OCT.2022 17:13:44




Date: 26.OCT.2022 17:13:58

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 26.OCT.2022 17:14:19

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 26.OCT.2022 17:14:40

Band 2_5 MHz_Middle_QPSK_RB25#0




Date: 26.OCT.2022 17:15:02


Band 2_5 MHz_Middle_16QAM_RB25#0




Date: 26.OCT.2022 17:15:23




Date: 26.OCT.2022 17:15:45



Date: 26.OCT.2022 17:16:09




Date: 26.OCT.2022 17:16:27




Date: 26.OCT.2022 17:16:43

Band 2_10 MHz_Middle_QPSK_RB50#0




Date: 26.OCT.2022 17:16:59


Band 2_10 MHz_Middle_16QAM_RB50#0




Date: 26.OCT.2022 17:17:17




Date: 26.OCT.2022 17:17:37



Date: 26.OCT.2022 17:17:52




Date: 26.OCT.2022 17:18:23




Date: 26.OCT.2022 17:18:44

Band 2_15 MHz_Middle_QPSK_RB75#0




Date: 26.OCT.2022 17:19:09


Band 2_15 MHz_Middle_16QAM_RB75#0



Date: 26.OCT.2022 17:19:33




Date: 26.OCT.2022 17:19:55




Date: 26.OCT.2022 17:20:19

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 26.OCT.2022 17:20:51

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 26.OCT.2022 17:21:12

Band 2_20 MHz_Middle_QPSK_RB100#0




Date: 26.OCT.2022 17:21:35

Band 2_20 MHz_Middle_16QAM_RB100#0




Date: 26.OCT.2022 17:21:56

Band 2_20 MHz_High_QPSK_RB100#0




Date: 26.OCT.2022 17:22:25


Band 2_20 MHz_High_16QAM_RB100#0



Date: 26.OCT.2022 17:22:49




Date: 26.OCT.2022 17:23:15




Date: 26.OCT.2022 17:23:39

Band 4_1.4 MHz_Middle_QPSK_RB6#0




Date: 26.OCT.2022 17:23:57


Band 4_1.4 MHz_Middle_16QAM_RB6#0



Date: 26.OCT.2022 17:24:17




Date: 26.OCT.2022 17:24:38



Date: 26.OCT.2022 17:24:56




Band 4_3 MHz_Middle_QPSK_RB15#0




Date: 26.OCT.2022 17:25:48


Band 4_3 MHz_Middle_16QAM_RB15#0




Date: 26.OCT.2022 17:26:02




Date: 26.OCT.2022 17:26:17



Date: 26.OCT.2022 17:26:32




Date: 26.OCT.2022 17:26:59




Date: 26.OCT.2022 17:27:20

Band 4_5 MHz_Middle_QPSK_RB25#0




Date: 26.OCT.2022 17:27:38

Band 4_5 MHz_Middle_16QAM_RB25#0




Date: 26.OCT.2022 17:28:00






Date: 26.OCT.2022 17:30:54




Date: 26.OCT.2022 17:31:12

Band 4_10 MHz_Middle_QPSK_RB50#0




Date: 26.OCT.2022 17:31:28

Band 4_10 MHz_Middle_16QAM_RB50#0




Date: 26.OCT.2022 17:31:44

Band 4_10 MHz_High_QPSK_RB50#0




Date: 26.OCT.2022 17:32:03


Band 4_10 MHz_High_16QAM_RB50#0



Date: 26.OCT.2022 17:32:22




Date: 26.OCT.2022 17:32:49




Date: 26.OCT.2022 17:33:14

Band 4_15 MHz_Middle_QPSK_RB75#0




Date: 26.OCT.2022 17:33:35


Band 4_15 MHz_Middle_16QAM_RB75#0



Date: 26.OCT.2022 17:34:00




Date: 26.OCT.2022 17:34:25




Date: 26.OCT.2022 17:34:49

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 26.OCT.2022 17:35:14

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 26.OCT.2022 17:35:39

Band 4_20 MHz_Middle_QPSK_RB100#0




Date: 26.OCT.2022 17:36:04


Band 4_20 MHz_Middle_16QAM_RB100#0




Date: 26.OCT.2022 17:36:29




Date: 26.OCT.2022 17:36:54




Date: 26.OCT.2022 17:37:19




Date: 26.OCT.2022 17:37:46




Date: 26.OCT.2022 17:38:10




Date: 26.OCT.2022 17:38:44




Date: 26.OCT.2022 17:39:08




Date: 26.OCT.2022 17:39:27



Date: 26.OCT.2022 17:39:48




Date: 26.OCT.2022 17:40:07



Date: 26.OCT.2022 17:40:25




Band 7_10 MHz_High_QPSK_RB50#0




Date: 26.OCT.2022 17:41:22


Band 7_10 MHz_High_16QAM_RB50#0



Date: 26.OCT.2022 17:41:41




Date: 26.OCT.2022 17:42:06




Date: 26.OCT.2022 17:42:30

Band 7_15 MHz_Middle_QPSK_RB75#0




Date: 26.OCT.2022 17:42:52


Band 7_15 MHz_Middle_16QAM_RB75#0




Date: 26.OCT.2022 17:43:20




Date: 26.OCT.2022 17:43:41



Date: 26.OCT.2022 17:44:06




Date: 26.OCT.2022 17:44:34




Date: 26.OCT.2022 17:44:58

Band 7_20 MHz_Middle_QPSK_RB100#0




Date: 26.OCT.2022 17:45:21

Band 7_20 MHz_Middle_16QAM_RB100#0




Date: 26.OCT.2022 17:45:42

Band 7_20 MHz_High_QPSK_RB100#0




Date: 26.OCT.2022 17:46:08


Band 7_20 MHz_High_16QAM_RB100#0



Date: 26.OCT.2022 17:46:29




Date: 27.OCT.2022 13:07:46




Date: 27.OCT.2022 13:08:03

Band 5_1.4 MHz_Middle_QPSK_RB6#0




Date: 27.OCT.2022 13:08:21


Band 5_1.4 MHz_Middle_16QAM_RB6#0




Date: 27.OCT.2022 13:08:38




Date: 27.OCT.2022 13:08:53




Date: 27.OCT.2022 13:09:10




Date: 27.OCT.2022 13:09:27




Date: 27.OCT.2022 13:09:44




Date: 27.OCT.2022 13:10:02




Date: 27.OCT.2022 13:10:23




Date: 27.OCT.2022 13:10:41



Date: 27.OCT.2022 13:10:55




Date: 27.OCT.2022 13:11:19




Date: 27.OCT.2022 13:11:37

Band 5_5 MHz_Middle_QPSK_RB25#0




Date: 27.OCT.2022 13:11:56


Band 5_5 MHz_Middle_16QAM_RB25#0




Date: 27.OCT.2022 13:12:14




Date: 27.OCT.2022 13:12:39



Date: 27.OCT.2022 13:12:56




Date: 27.OCT.2022 13:13:18




Date: 27.OCT.2022 13:13:33

Band 5_10 MHz_Middle_QPSK_RB50#0




Date: 27.OCT.2022 13:13:53


Band 5_10 MHz_Middle_16QAM_RB50#0




Date: 27.OCT.2022 13:14:11




Date: 27.OCT.2022 13:14:33



Date: 27.OCT.2022 13:14:52




Date: 27.OCT.2022 18:38:01




Date: 27.OCT.2022 18:38:34

Band 38_5 MHz_Middle_QPSK_RB25#0




Date: 27.OCT.2022 18:38:56


Band 38_5 MHz_Middle_16QAM_RB25#0



Date: 27.OCT.2022 18:39:20




Date: 27.OCT.2022 18:39:51




Date: 27.OCT.2022 18:40:22

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 27.OCT.2022 18:40:52

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 27.OCT.2022 18:41:11

Band 38_10 MHz_Middle_QPSK_RB50#0




Date: 27.OCT.2022 18:41:36

Band 38_10 MHz_Middle_16QAM_RB50#0




Date: 27.OCT.2022 18:41:55

Band 38_10 MHz_High_QPSK_RB50#0




Date: 27.OCT.2022 18:42:20


Band 38_10 MHz_High_16QAM_RB50#0



Date: 27.OCT.2022 18:42:45




Date: 27.OCT.2022 18:43:18




Date: 27.OCT.2022 18:43:42

Band 38_15 MHz_Middle_QPSK_RB75#0




Date: 27.OCT.2022 18:44:23

Band 38_15 MHz_Middle_16QAM_RB75#0




Date: 27.OCT.2022 18:44:47

Band 38_15 MHz_High_QPSK_RB75#0




Date: 27.OCT.2022 18:45:28

Band 38_15 MHz_High_16QAM_RB75#0




Date: 27.OCT.2022 18:45:52

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 27.OCT.2022 18:46:20

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 27.OCT.2022 18:46:47

Band 38_20 MHz_Middle_QPSK_RB100#0




Date: 27.OCT.2022 18:47:19

Band 38_20 MHz_Middle_16QAM_RB100#0




Date: 27.OCT.2022 18:47:40

Band 38_20 MHz_High_QPSK_RB100#0




Date: 27.OCT.2022 18:48:05

Band 38_20 MHz_High_16QAM_RB100#0




Date: 27.OCT.2022 18:48:27

Band 26_1.4 MHz_Low_QPSK_RB6#0




Date: 4.NOV.2022 17:15:53

Band 26_1.4 MHz_Low_16QAM_RB6#0




Date: 4.NOV.2022 17:16:08

Band 26_1.4 MHz_Middle_QPSK_RB6#0




Date: 4.NOV.2022 17:16:27


Band 26_1.4 MHz_Middle_16QAM_RB6#0




Date: 4.NOV.2022 17:16:48




Date: 4.NOV.2022 17:17:06



Date: 4.NOV.2022 17:17:24




Date: 4.NOV.2022 17:17:41




Date: 4.NOV.2022 17:17:59







Date: 4.NOV.2022 17:18:51



Date: 4.NOV.2022 17:19:06




Date: 4.NOV.2022 17:19:36




Date: 4.NOV.2022 17:19:55

Band 26_5 MHz_Middle_QPSK_RB25#0




Date: 4.NOV.2022 17:20:14


Band 26_5 MHz_Middle_16QAM_RB25#0



Date: 4.NOV.2022 17:20:33




Date: 4.NOV.2022 17:20:52




Date: 4.NOV.2022 17:21:11

Band 26_10 MHz_Middle_QPSK_RB50#0




Date: 4.NOV.2022 17:21:32


Band 26_10 MHz_Middle_16QAM_RB50#0



Date: 4.NOV.2022 17:21:52




Date: 4.NOV.2022 17:01:38




Date: 4.NOV.2022 17:02:00

Band 26_15 MHz_Middle_QPSK_RB75#0




Date: 4.NOV.2022 17:02:25


Band 26_15 MHz_Middle_16QAM_RB75#0



Date: 4.NOV.2022 17:02:51



Date: 4.NOV.2022 17:03:13



Date: 4.NOV.2022 17:03:35