

Prüfbericht - Nr.:

50103122 001


Test Report No.

Seite 1 von 14

Page 1 of 14


6 dB Bandwidth Measurement

TX frequency: 2402MHz



Date: 27.OCT.2017 14:55:28

TX frequency: 2440MHz



Date: 27.OCT.2017 15:00:23

Prüfbericht - Nr.:


50103122 001

Seite 2 von 14

Test Report No.

Page 2 of 14

TX frequency: 2480MHz



Date: 27.OCT.2017 15:16:07

Prüfbericht - Nr.:

50103122 001


Seite 3 von 14

Test Report No.

Page 3 of 14


Maximum Peak Conducted Output power

TX frequency: 2402MHz



Date: 27.OCT.2017 14:55:57

TX frequency: 2440MHz



Date: 27.OCT.2017 15:00:43

Prüfbericht - Nr.:


50103122 001

Seite 4 von 14

Test Report No.

Page 4 of 14

TX frequency: 2480MHz



Date: 27.OCT.2017 15:16:33

Prüfbericht - Nr.:

50103122 001


Test Report No.

Seite 5 von 14

Page 5 of 14


Power Spectral Density

TX frequency: 2402MHz



Date: 27.OCT.2017 14:56:23

TX frequency: 2440MHz



Date: 27.OCT.2017 15:01:05

Prüfbericht - Nr.:


50103122 001

Seite 6 von 14

Test Report No.

Page 6 of 14

TX frequency: 2480MHz



Date: 27.OCT.2017 15:17:26

Prüfbericht - Nr.:

50103122 001


Seite 7 von 14

Test Report No.


Page 7 of 14

Spurious Conducted Emissions

TX frequency: 2402MHz



Date: 27.OCT.2017 14:57:33



Date: 27.OCT.2017 14:58:20


Prüfbericht - Nr.:

50103122 001


Seite 8 von 14

Test Report No.

Page 8 of 14



Date: 27.OCT.2017 14:59:07



Date: 27.OCT.2017 14:59:30


Prüfbericht - Nr.:

50103122 001

Seite 9 von 14

Test Report No.

Page 9 of 14



Date: 27.OCT.2017 14:57:05

Prüfbericht - Nr.:


50103122 001

Seite 10 von 14


Test Report No.

Page 10 of 14

TX frequency: 2440MHz



Date: 27.OCT.2017 15:01:42



Date: 27.OCT.2017 15:05:04


Prüfbericht - Nr.:

50103122 001


Seite 11 von 14

Test Report No.

Page 11 of 14



Date: 27.OCT.2017 15:06:10



Date: 27.OCT.2017 15:14:38

Prüfbericht - Nr.:


50103122 001

Seite 12 von 14


Test Report No.

Page 12 of 14

TX frequency: 2480MHz



Date: 27.OCT.2017 15:19:16



Date: 27.OCT.2017 15:19:54


Prüfbericht - Nr.:

50103122 001


Seite 13 von 14

Test Report No.

Page 13 of 14




Date: 27.OCT.2017 15:20:19



Date: 27.OCT.2017 15:20:43

Prüfbericht - Nr.: 50103122 001
Test Report No.

Seite 14 von 14
Page 14 of 14



Date: 27.OCT.2017 15:21:24