141mm

80mm

TYLT

mini boom

WARNING
Don't short-circuit the mini boom
as this can cause excessive heat and fire.
Don't store mini boom in hot areas
or dispose of it in a fire.
Don't disassemble or modify the mini boom
as there are no user serviceable parts inside.
When the mini boom is worn out dispose
of it at an electronics recycling center.



IC3782

Company: TYLT ESSENTIALS
Designer: MD
Part #: IC3782
Date: 4/18/17

Colors: 1/0
Material: 20PT SBS
Size (Flat): 141mm W X 80mm H
Instructions: 2 vertical folds

BLACK

FCC Warning

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:
(1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

NOTE 1: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:
- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
-Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
-Consult the dealer or an experienced radio/TV technician for help.

NOTE 2: Any changes or modifications to this unit not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.