

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AODE-RFUGSB
17-0454
March 7, 2018
Asymmetric Technologies
RFUGS Model B

EXTERNAL PHOTOGRAPHS




Figure 1. EUT Complete Assembly

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AODE-RFUGSB
17-0454
March 7, 2018
Asymmetric Technologies
RFUGS Model B



Figure 2. EUT with Antenna Shaft Removed

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AODE-RFUGSB
17-0454
March 7, 2018
Asymmetric Technologies
RFUGS Model B



Figure 3. Side 1

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AODE-RFUGSB
17-0454
March 7, 2018
Asymmetric Technologies
RFUGS Model B



Figure 4. Back Side

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AODE-RFUGSB
17-0454
March 7, 2018
Asymmetric Technologies
RFUGS Model B



Figure 5. Side 2

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AODE-RFUGSB
17-0454
March 7, 2018
Asymmetric Technologies
RFUGS Model B




Figure 6. Bottom Side