










Shenzhen Anbotech Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotech.com E-mail: service@anbotech.com












Shenzhen Anbotech Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotech.com E-mail: service@anbotech.com










Shenzhen Anbotech Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotech.com E-mail: service@anbotech.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotech Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.








Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com








Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotech Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Appendix D: Maximum Power Spectral Density

Test Result B1/2/3

Test Mode	Antenna	Frequency [MHz]	Reading Result [dBm/MHz]	DC Factor [dBm]	Result [dBm]	Limit [dBm/MHz]	Verdict
11A	Ant1	5180	-3.46	0.00	-3.46	≤17.00	PASS
11A	Ant1	5220	-4.01	0.00	-4.01	≤17.00	PASS
11A	Ant1	5240	-4.59	0.00	-4.59	≤17.00	PASS
11A	Ant1	5260	-4.99	0.00	-4.99	≤11.00	PASS
11A	Ant1	5300	-1.95	0.00	-1.95	≤11.00	PASS
11A	Ant1	5320	-1.79	0.00	-1.79	≤11.00	PASS
11A	Ant1	5500	0.33	0.00	0.33	≤11.00	PASS
11A	Ant1	5580	-0.19	0.00	-0.19	≤11.00	PASS
11A	Ant1	5700	-1.68	0.00	-1.68	≤11.00	PASS
11N20SISO	Ant1	5180	-3.93	0.00	-3.93	≤17.00	PASS
11N20SISO	Ant1	5220	-4.57	0.00	-4.57	≤17.00	PASS
11N20SISO	Ant1	5240	-4.74	0.00	-4.74	≤17.00	PASS
11N20SISO	Ant1	5260	-5.31	0.00	-5.31	≤11.00	PASS
11N20SISO	Ant1	5300	-1.96	0.00	-1.96	≤11.00	PASS
11N20SISO	Ant1	5320	-2.02	0.00	-2.02	≤11.00	PASS
11N20SISO	Ant1	5500	-0.11	0.00	-0.11	≤11.00	PASS
11N20SISO	Ant1	5580	-0.63	0.00	-0.63	≤11.00	PASS
11N20SISO	Ant1	5700	-2.13	0.00	-2.13	≤11.00	PASS
11AC20SISO	Ant1	5180	-3.73	0.00	-3.73	≤17.00	PASS
11AC20SISO	Ant1	5220	-4.24	0.00	-4.24	≤17.00	PASS
11AC20SISO	Ant1	5240	-4.40	0.00	-4.40	≤17.00	PASS
11AC20SISO	Ant1	5260	-5.15	0.00	-5.15	≤11.00	PASS
11AC20SISO	Ant1	5300	-1.98	0.00	-1.98	≤11.00	PASS
11AC20SISO	Ant1	5320	-1.67	0.00	-1.67	≤11.00	PASS
11AC20SISO	Ant1	5500	0.42	0.00	0.42	≤11.00	PASS
11AC20SISO	Ant1	5580	-0.44	0.00	-0.44	≤11.00	PASS
11AC20SISO	Ant1	5700	-1.91	0.00	-1.91	≤11.00	PASS
11AX20SISO	Ant1	5180	-4.04	0.00	-4.04	≤17.00	PASS
11AX20SISO	Ant1	5220	-4.36	0.00	-4.36	≤17.00	PASS
11AX20SISO	Ant1	5240	-4.83	0.00	-4.83	≤17.00	PASS
11AX20SISO	Ant1	5260	-5.19	0.00	-5.19	≤11.00	PASS
11AX20SISO	Ant1	5300	-2.24	0.00	-2.24	≤11.00	PASS
11AX20SISO	Ant1	5320	-2.07	0.00	-2.07	≤11.00	PASS
11AX20SISO	Ant1	5500	-0.14	0.00	-0.14	≤11.00	PASS
11AX20SISO	Ant1	5580	-0.81	0.00	-0.81	≤11.00	PASS
11AX20SISO	Ant1	5700	-1.97	0.00	-1.97	≤11.00	PASS

Note: 1.The Duty Cycle Factor and cable loss are compensated in the graph.


Test Result B4

Test Mode	Antenna	Frequency[MHz]	Reading Result[dBm/510KHz]	DC Factor [dBm]	Result [dBm/500 KHz]	Limit [dBm/500 KHz]	Verdict
11A	Ant1	5745	-4.84	0.00	-4.93	≤30.00	PASS
11A	Ant1	5785	-5.58	0.00	-5.67	≤30.00	PASS
11A	Ant1	5825	-5.19	0.00	-5.28	≤30.00	PASS
11N20SISO	Ant1	5745	-5.13	0.00	-5.22	≤30.00	PASS
11N20SISO	Ant1	5785	-6.26	0.00	-6.35	≤30.00	PASS
11N20SISO	Ant1	5825	-5.57	0.00	-5.66	≤30.00	PASS
11AC20SISO	Ant1	5745	-4.80	0.00	-4.89	≤30.00	PASS
11AC20SISO	Ant1	5785	-5.57	0.00	-5.66	≤30.00	PASS
11AC20SISO	Ant1	5825	-5.52	0.00	-5.61	≤30.00	PASS
11AX20SISO	Ant1	5745	-5.24	0.00	-5.33	≤30.00	PASS
11AX20SISO	Ant1	5785	-5.93	0.00	-6.02	≤30.00	PASS
11AX20SISO	Ant1	5825	-5.56	0.00	-5.65	≤30.00	PASS

Note:

1. The cable loss and RBW Factor are compensated in the graph.
2. Result [dBm/500KHz]=Result [dBm/510KHz]+10*LOG10(500/510)


Test Graphs B1/2/3



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com






Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com


Test GraphsB4



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Appendix E: Band edge measurements

Test Result B1/2/3

Test Mode	Antenna	ChName	Frequency[MHz]	Result[dBm]	Limit[dBm]	Verdict
11A	Ant1	Low	5180	-44.91	≤-27	PASS
11A	Ant1	High	5320	-44.6	≤-27	PASS
11A	Ant1	Low	5500	-43.46	≤-27	PASS
11A	Ant1	High	5700	-37.99	≤-27	PASS
11N20SISO	Ant1	Low	5180	-45.05	≤-27	PASS
11N20SISO	Ant1	High	5320	-44.45	≤-27	PASS
11N20SISO	Ant1	Low	5500	-44.15	≤-27	PASS
11N20SISO	Ant1	High	5700	-38.62	≤-27	PASS
11AC20SISO	Ant1	Low	5180	-44.9	≤-27	PASS
11AC20SISO	Ant1	High	5320	-44.76	≤-27	PASS
11AC20SISO	Ant1	Low	5500	-45.38	≤-27	PASS
11AC20SISO	Ant1	High	5700	-37.58	≤-27	PASS
11AX20SISO	Ant1	Low	5180	-45.1	≤-27	PASS
11AX20SISO	Ant1	High	5320	-45.45	≤-27	PASS
11AX20SISO	Ant1	Low	5500	-44.34	≤-27	PASS
11AX20SISO	Ant1	High	5700	-39.45	≤-27	PASS

Note: 1. The margin plus the antenna gain also meets the limit.

2. Regarding the spurious emissions from 30MHz to 26.5GHz, the cable lose have been set in the 'offset' of the Spectrum Analyzer during the test.