

深圳安博检测股份有限公司
Shenzhen Anbotek Compliance Laboratory Limited



Date

Dec. 12, 2018

Federal Communications Commission
Office of Engineering and Technology
445 12th ST SW
Washington, DC 20554

RE: Request for Change in ID

<Original Grantee Holder Anker Innovations Limited> Original FCC ID: <2AOKB-A2518>

Original Grant Date: <Nov. 19, 2018>

<New Grantee Holder Anker Innovations Limited> New FCC ID: <2AOKBA2518>

To Whom It May Concern:

<New Grantee Holder Anker Innovations Limited> verifies the equipment bearing the modified identification does not differ from the original equipment, there are no differences in terms of both hardware and software. The only difference is the FCC ID number: the FCC ID of original equipment has a symbol “-”, which is deleted in the FCC ID of the equipment bearing the changed identification <New Grantee Holder Anker Innovations Limited>. Our engineer used to add a symbol “-” between Grantee Code and Product Code, but the customers didn't actually need it, and they have already printed the logo, so we needed to change the ID number.

The original test results continue to be representative of and applicable to the equipment bearing the changed identification.

If you required any additional information, please contact us.

Regards,

Signature



New Grantee Holder Contact Name

Simon Zhang

New Grantee Holder Company Name

Anker Innovations Limited

Phone: 0731-88709535

Fax: 0731-88709538

Email: Simon.zhang@oceanwing.com