


Internal Photos
VMC2080 & VMC3080 Pic 1




VMC2080 & VMC3080 Pic 2



Underwriters Laboratories Taiwan Co., Ltd.

Building A, B and E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan
Telephone : +886-2-7737-3000
Facsimile (FAX) : +886-3-583-7948

VMC2080 & VMC3080 Pic 3



VMC2080 & VMC3080 Pic 4



Underwriters Laboratories Taiwan Co., Ltd.

Building A, B and E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948


VMC2080 & VMC3080 Pic 5




VMC2080 & VMC3080 Pic 6



VMC2080 & VMC3080 Pic 7




VMC2080 & VMC3080 Pic 8




Underwriters Laboratories Taiwan Co., Ltd.

Building A, B and E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan
Telephone : +886-2-7737-3000
Facsimile (FAX) : +886-3-583-7948


VMC2080 & VMC3080 Pic 9



VMC2080 & VMC3080 Pic 10



VMC2080 & VMC3080 Pic 11



VMC2080 & VMC3080 Pic 12



Underwriters Laboratories Taiwan Co., Ltd.

Building A, B and E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000

Facsimile (FAX) :+886-3-583-7948

VMC2080 & VMC3080 Pic 13**VMC2080 & VMC3080 Pic 14****Underwriters Laboratories Taiwan Co., Ltd.**

Building A, B and E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone :+886-2-7737-3000

Facsimile (FAX) :+886-3-583-7948

VMC2080 & VMC3080 Pic 15



VMC2080 & VMC3080 Pic 16




Underwriters Laboratories Taiwan Co., Ltd.

Building A, B and E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000

Facsimile (FAX) :+886-3-583-7948

VMC2080 & VMC3080 Pic 17




VMC2080 & VMC3080 Pic 18




VMC2080 & VMC3080 Pic 19



VMC2080 & VMC3080 Pic 20




VMC2080 & VMC3080 Pic 21




VMC2080 & VMC3080 Pic 22




VMC2080 & VMC3080 Pic 23




VMC2080 & VMC3080 Pic 24




VMC2080 & VMC3080 Pic 25




VMC2080 & VMC3080 Pic 26




VMC2080 & VMC3080 Pic 27




VMC2080 & VMC3080 Pic 28




VMC2080 & VMC3080 Pic 29




VMC2080 & VMC3080 Pic 30




VMC2080 & VMC3080 Pic 31




VMC2080 & VMC3080 Pic 32



VMC2080 & VMC3080 Pic 33



VMC2080 & VMC3080 Pic 34




RF IC (WLAN)

VMC2080 & VMC3080 Pic 35



RF IC (BLE)

VMC2080 & VMC3080 Pic 36




Underwriters Laboratories Taiwan Co., Ltd.

Building A, B and E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948


VMC2080 & VMC3080 Pic 37




VMC2080 & VMC3080 Pic 38



VMC2080 & VMC3080 Pic 39




VMC2080 & VMC3080 Pic 40




VMC2080 & VMC3080 Pic 41




VMC2080 & VMC3080 Pic 42




VMC2080 & VMC3080 Pic 43



VMC2080 & VMC3080 Pic 44



VMC2080 & VMC3080 Pic 45



VMC2080 & VMC3080 Pic 46

