




SanDisk









Antenna 1
0014EE0C6F51
Antenna 2



1703221
APH
0014EE0C6F50



0014EE0C6F51



0014EE0C6F51




CON9
C185
CON7
R318
C186
C286
H11
H10
C233
C252
C287
R325
C267
H7
H9
C285
CON8
C194
TP20
TP21


Ant2-V4



Ant1-V4


1703221
APH
0014EE0C6F50


4.0TB
WD Blue™




4.0TB
WD Blue™
S/N : WXM1E979V29H
MDL : WD40NPZZ-00PDPT0
MSIP-REM-WDT-0022
Product of Malaysia
D33015
RoHS
FRAGILE
E101559
CAN ICES-3 (B)/ NMB-3(B)
Product warranty will be void if seal, label or cover is removed or damaged.
Do not cover any drive holes
R/N: 800022 5VDC: 0.39A
DATE: 09 JAN 2018 DCX: 9P09D97PV
WWN:50014EE6B2F3B8AE
U.S. Patents: 6178056, 5956196, 6289484, 6263459






WD
www.wd.com
S/N:WXA1A97HHD7H
2TB
WD20SPZX
MDL:WD20SPZX-11CRATO
WWN:50014EE60830A641
台北市敦化北路205號14樓1402室
WD NL B.V. Taurusavenue
5, 2132 LS Hoofddorp NL
CAN ICES-3 (B)/
NMB-3(B)
DCM:HHNT2HN
DCX:HC07R96AH
5VDC:0.55A
DATE:22 DEC 2017
Product of Malaysia
WD Blue
FRAGILE
E101559
D33015
RoHS
Not For Resale
U.S. Patents: 6178056, 5956196,6289484, 6263459


1TB
Not For Resale
WD Blue




WD
www.wd.com
1TB
WD10SPZX
Do not cover
any drive holes.
Do not press
on top cover.
Not For Resale
台北市敦化北路205號14樓1402室
FRAGILE
Product warranty will be void if seal,
label or cover is removed or damaged.
WD NL B.V. Taurusavenue 5, 2132
LS Hoofddorp NL
WWN:50014EE6083E2B9B
DCM : HHNT2HB
DCX : 3Z0118400
DATE: 03 JAN 2018
Product of
Malaysia
5VDC : 0.55A
CAN ICES-3 (B)/
NMB-3(B)
D33015
RoHS
E101559
U.S. Patents: 6178056, 5956196,6289484, 6263459
S/N:WXN1A8730Y1F
MDL:WD10SPZX-11Z10T0
WD Blue™