

Bolt Modus Corp

Address: Oficina N.33 Edificio Ofidepositos Central, Calidonia - Distrito Federal,
Panama

Tel.: 13056144478

Email: gbriceno@yeyzcorp.com

Date: 2020-05-12

FEDERAL COMMUNICATIONS COMMISSIONS

Authorization and Evaluation Division

7435 Oakland Mills Road

Columbia, MD 21046

Attestation letter

Dear Sir or Madam,

The RF chip, model: MT6177M installed in our product Smart phone; Model number: LIV2LTE, FCC ID: 2APW4LIV2L, which supports GSM/WCDMA/LTE function.

For use in the US market, this chip only support GSM 850/1900, WCDMA Band 2/5, LTE band 2/4/7/12/17, the other LTE/WCDMA bands was disabled by the manufacturer in the software. The end user has no capability to activate it.

The RF chip, model: MT6625L installed in our product Smart phone; Model number: LIV2LTE, FCC ID: 2APW4LIV2L, which supports 2.4G WiFi/5G WiFi function. For use in the US market, this chip only support 2.4G WiFi, 5G WiFi was disabled by the manufacturer in the software. The end user has no capability to activate it.

Sincerely,

Signature



Giovanna Briceño
Homologation leader

