



May 31, 2018

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

Re: Request to Change in Identification:

Dear Examiner,

This change of identification request applies for FCC ID: 2APZK-WAM01 as established in 47CFR 2.933(b) for a currently approved device. This application by __ Cummins Inc. __ will establish a new FCC ID: 2APZK-WAM01 under __ Cummins Inc. __ Grantee code for purpose of marketing. The original grant to __ LSR __ will remain in effect per 2.933(b).

1. The original identification is FCC ID: TFB-BLECA
2. The original grant date is 09/25/2013
3. The equipment is electrically identical, only application and FCC ID are different
4. The original test results are applicable and representative of this changed device
5. Exterior photographs are include in this application

The following files are electronically submitted as attachments:

Authorization letter from original grantee
External Photos of New Application
FCC ID Label Format and location of New Application

Sincerely,

A handwritten signature in black ink, appearing to read 'William D Meyer'.

William D Meyer
Chief Engineer, Cummins Electronics

Cummins Inc.
MC14750
500 Central Avenue
Columbus, IN 47201
Tel (812) 374 2239
Fax (812) 377 1452
cummins.com