


Reference No.: WTS18S09122875-5W

Internal Photos





Reference No.: WTS18S09122875-5W




Reference No.: WTS18S09122875-5W





Reference No.: WTS18S09122875-5W




Reference No.: WTS18S09122875-5W




Reference No.: WTS18S09122875-5W




Waltek Services (Shenzhen) Co.,Ltd.
http://www.waltek.com.cn



Reference No.: WTS18S09122875-5W




Reference No.: WTS18S09122875-5W





Ant.3 port

Ant.2 port


Ant.1 port



Reference No.: WTS18S09122875-5W



Reference No.: WTS18S09122875-5W




Waltek Services (Shenzhen) Co.,Ltd.
<http://www.waltek.com.cn>

Reference No.: WTS18S09122875-5W




Ant.5 port


Ant.4 port



Reference No.: WTS18S09122875-5W



Reference No.: WTS18S09122875-5W



=====End=====