




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM QPSK_3570MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM QPSK_3624.99MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM QPSK_3679.98MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM 16 QAM_3570MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16 QAM_3624.99MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16 QAM_3679.98MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM 64 QAM_3570MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM 64 QAM_3624.99MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM 64 QAM_3679.98MHz_Outer_Full



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM 256 QAM_3570MHz_Outer_Full



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM 256 QAM_3624.99MHz_Outer_Full



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM 256 QAM_3679.98MHz_Outer_Full

