

11AC20SISO-Ant1-5580



11AC20SISO-Ant1-5700

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



11AC20SISO-Ant1-5745



11AC20SISO-Ant1-5785

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.
Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AC20SISO-Ant1-5825



11AC40SISO-Ant1-5190

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



11AC40SISO-Ant1-5230



11AC40SISO-Ant1-5270

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AC40SISO-Ant1-5310



11AC40SISO-Ant1-5510

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AC40SISO-Ant1-5550



11AC40SISO-Ant1-5670

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AC40SISO-Ant1-5755



11AC40SISO-Ant1-5795

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



11AC80SISO-Ant1-5210



11AC80SISO-Ant1-5290

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AC80SISO-Ant1-5530



11AC80SISO-Ant1-5775

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



11AX20SISO-Ant1-5180



11AX20SISO-Ant1-5220

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX20SISO-Ant1-5240



11AX20SISO-Ant1-5260

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



11AX20SISO-Ant1-5300



11AX20SISO-Ant1-5320

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX20SISO-Ant1-5500



11AX20SISO-Ant1-5580

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX20SISO-Ant1-5700



11AX20SISO-Ant1-5745

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX20SISO-Ant1-5785



11AX20SISO-Ant1-5825

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX40SISO-Ant1-5190



11AX40SISO-Ant1-5230

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



11AX40SISO-Ant1-5270



11AX40SISO-Ant1-5310

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX40SISO-Ant1-5510



11AX40SISO-Ant1-5550

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX40SISO-Ant1-5670



11AX40SISO-Ant1-5755

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



11AX40SISO-Ant1-5795



11AX80SISO-Ant1-5210

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX80SISO-Ant1-5290



11AX80SISO-Ant1-5530

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX80SISO-Ant1-5775

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Appendix A3: Minimum 6dB Bandwidth

Test Result B4

Test Mode	Antenna	Frequency[MHz]	6db EBW [MHz]	FL[MHz]	FH[MHz]	Limit[MHz]	Verdict
11A	Ant1	5745	16.400	5736.760	5753.160	0.5	PASS
11A	Ant1	5785	16.320	5776.800	5793.120	0.5	PASS
11A	Ant1	5825	16.400	5816.760	5833.160	0.5	PASS
11N20SISO	Ant1	5745	17.600	5736.160	5753.760	0.5	PASS
11N20SISO	Ant1	5785	17.600	5776.160	5793.760	0.5	PASS
11N20SISO	Ant1	5825	17.640	5816.120	5833.760	0.5	PASS
11N40SISO	Ant1	5755	36.400	5736.760	5773.160	0.5	PASS
11N40SISO	Ant1	5795	36.320	5776.760	5813.080	0.5	PASS
11AC20SISO	Ant1	5745	17.600	5736.160	5753.760	0.5	PASS
11AC20SISO	Ant1	5785	17.600	5776.160	5793.760	0.5	PASS
11AC20SISO	Ant1	5825	17.600	5816.160	5833.760	0.5	PASS
11AC40SISO	Ant1	5755	36.400	5736.760	5773.160	0.5	PASS
11AC40SISO	Ant1	5795	36.320	5776.760	5813.080	0.5	PASS
11AC80SISO	Ant1	5775	76.320	5736.760	5813.080	0.5	PASS
11AX20SISO	Ant1	5745	18.880	5735.600	5754.480	0.5	PASS
11AX20SISO	Ant1	5785	19.040	5775.440	5794.480	0.5	PASS
11AX20SISO	Ant1	5825	18.960	5815.480	5834.440	0.5	PASS
11AX40SISO	Ant1	5755	37.920	5736.040	5773.960	0.5	PASS
11AX40SISO	Ant1	5795	38.080	5775.960	5814.040	0.5	PASS
11AX80SISO	Ant1	5775	77.920	5735.960	5813.880	0.5	PASS

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.
Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Test Graphs B4



11A-Ant1-5745-PASS



11A-Ant1-5785-PASS

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.
Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11A-Ant1-5825-PASS



11N20SISO-Ant1-5745-PASS

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



11N20SISO-Ant1-5785-PASS



11N20SISO-Ant1-5825-PASS

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



11N40SISO-Ant1-5755-PASS



11N40SISO-Ant1-5795-PASS

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



11AC20SISO-Ant1-5745-PASS



11AC20SISO-Ant1-5785-PASS

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



11AC20SISO-Ant1-5825-PASS



11AC40SISO-Ant1-5755-PASS

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



11AC40SISO-Ant1-5795-PASS



11AC80SISO-Ant1-5775-PASS

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



11AX20SISO-Ant1-5745-PASS



11AX20SISO-Ant1-5785-PASS

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



11AX20SISO-Ant1-5825-PASS



11AX40SISO-Ant1-5755-PASS

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX40SISO-Ant1-5795-PASS



11AX80SISO-Ant1-5775-PASS

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Appendix B: Duty Cycle

Test Result

Test Mode	Antenna	Frequency [MHz]	Transmission Duration [ms]	Transmission Period [ms]	Duty Cycle [%]	Dc Factor [dB]	1/T
11A	Ant1	5180	100.00	100.00	100.00	0.00	0.01
11A	Ant1	5220	100.00	100.00	100.00	0.00	0.01
11A	Ant1	5240	100.00	100.00	100.00	0.00	0.01
11A	Ant1	5260	100.00	100.00	100.00	0.00	0.01
11A	Ant1	5300	100.00	100.00	100.00	0.00	0.01
11A	Ant1	5320	100.00	100.00	100.00	0.00	0.01
11A	Ant1	5500	100.00	100.00	100.00	0.00	0.01
11A	Ant1	5580	100.00	100.00	100.00	0.00	0.01
11A	Ant1	5700	100.00	100.00	100.00	0.00	0.01
11A	Ant1	5745	100.00	100.00	100.00	0.00	0.01
11A	Ant1	5785	100.00	100.00	100.00	0.00	0.01
11A	Ant1	5825	100.00	100.00	100.00	0.00	0.01
11N20SISO	Ant1	5180	100.00	100.00	100.00	0.00	0.01
11N20SISO	Ant1	5220	100.00	100.00	100.00	0.00	0.01
11N20SISO	Ant1	5240	100.00	100.00	100.00	0.00	0.01
11N20SISO	Ant1	5260	100.00	100.00	100.00	0.00	0.01
11N20SISO	Ant1	5300	100.00	100.00	100.00	0.00	0.01
11N20SISO	Ant1	5320	100.00	100.00	100.00	0.00	0.01
11N20SISO	Ant1	5500	100.00	100.00	100.00	0.00	0.01
11N20SISO	Ant1	5580	100.00	100.00	100.00	0.00	0.01
11N20SISO	Ant1	5700	100.00	100.00	100.00	0.00	0.01
11N20SISO	Ant1	5745	100.00	100.00	100.00	0.00	0.01
11N20SISO	Ant1	5785	100.00	100.00	100.00	0.00	0.01
11N20SISO	Ant1	5825	100.00	100.00	100.00	0.00	0.01
11N40SISO	Ant1	5190	100.00	100.00	100.00	0.00	0.01
11N40SISO	Ant1	5230	100.00	100.00	100.00	0.00	0.01
11N40SISO	Ant1	5270	100.00	100.00	100.00	0.00	0.01
11N40SISO	Ant1	5310	100.00	100.00	100.00	0.00	0.01
11N40SISO	Ant1	5510	100.00	100.00	100.00	0.00	0.01
11N40SISO	Ant1	5550	100.00	100.00	100.00	0.00	0.01
11N40SISO	Ant1	5670	100.00	100.00	100.00	0.00	0.01
11N40SISO	Ant1	5755	100.00	100.00	100.00	0.00	0.01
11N40SISO	Ant1	5795	100.00	100.00	100.00	0.00	0.01
11AC20SISO	Ant1	5180	100.00	100.00	100.00	0.00	0.01
11AC20SISO	Ant1	5220	100.00	100.00	100.00	0.00	0.01
11AC20SISO	Ant1	5240	100.00	100.00	100.00	0.00	0.01

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.
Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

11AC20SISO	Ant1	5260	100.00	100.00	100.00	0.00	0.01
11AC20SISO	Ant1	5300	100.00	100.00	100.00	0.00	0.01
11AC20SISO	Ant1	5320	100.00	100.00	100.00	0.00	0.01
11AC20SISO	Ant1	5500	100.00	100.00	100.00	0.00	0.01
11AC20SISO	Ant1	5580	100.00	100.00	100.00	0.00	0.01
11AC20SISO	Ant1	5700	100.00	100.00	100.00	0.00	0.01
11AC20SISO	Ant1	5745	100.00	100.00	100.00	0.00	0.01
11AC20SISO	Ant1	5785	100.00	100.00	100.00	0.00	0.01
11AC20SISO	Ant1	5825	100.00	100.00	100.00	0.00	0.01
11AC40SISO	Ant1	5190	100.00	100.00	100.00	0.00	0.01
11AC40SISO	Ant1	5230	100.00	100.00	100.00	0.00	0.01
11AC40SISO	Ant1	5270	100.00	100.00	100.00	0.00	0.01
11AC40SISO	Ant1	5310	100.00	100.00	100.00	0.00	0.01
11AC40SISO	Ant1	5510	100.00	100.00	100.00	0.00	0.01
11AC40SISO	Ant1	5550	100.00	100.00	100.00	0.00	0.01
11AC40SISO	Ant1	5670	100.00	100.00	100.00	0.00	0.01
11AC40SISO	Ant1	5755	100.00	100.00	100.00	0.00	0.01
11AC40SISO	Ant1	5795	100.00	100.00	100.00	0.00	0.01
11AC80SISO	Ant1	5210	100.00	100.00	100.00	0.00	0.01
11AC80SISO	Ant1	5290	100.00	100.00	100.00	0.00	0.01
11AC80SISO	Ant1	5530	100.00	100.00	100.00	0.00	0.01
11AC80SISO	Ant1	5775	100.00	100.00	100.00	0.00	0.01
11AX20SISO	Ant1	5180	100.00	100.00	100.00	0.00	0.01
11AX20SISO	Ant1	5220	100.00	100.00	100.00	0.00	0.01
11AX20SISO	Ant1	5240	100.00	100.00	100.00	0.00	0.01
11AX20SISO	Ant1	5260	100.00	100.00	100.00	0.00	0.01
11AX20SISO	Ant1	5300	100.00	100.00	100.00	0.00	0.01
11AX20SISO	Ant1	5320	100.00	100.00	100.00	0.00	0.01
11AX20SISO	Ant1	5500	100.00	100.00	100.00	0.00	0.01
11AX20SISO	Ant1	5580	100.00	100.00	100.00	0.00	0.01
11AX20SISO	Ant1	5700	100.00	100.00	100.00	0.00	0.01
11AX20SISO	Ant1	5745	100.00	100.00	100.00	0.00	0.01
11AX20SISO	Ant1	5785	100.00	100.00	100.00	0.00	0.01
11AX20SISO	Ant1	5825	100.00	100.00	100.00	0.00	0.01
11AX40SISO	Ant1	5190	100.00	100.00	100.00	0.00	0.01
11AX40SISO	Ant1	5230	100.00	100.00	100.00	0.00	0.01
11AX40SISO	Ant1	5270	100.00	100.00	100.00	0.00	0.01
11AX40SISO	Ant1	5310	100.00	100.00	100.00	0.00	0.01
11AX40SISO	Ant1	5510	100.00	100.00	100.00	0.00	0.01
11AX40SISO	Ant1	5550	100.00	100.00	100.00	0.00	0.01
11AX40SISO	Ant1	5670	100.00	100.00	100.00	0.00	0.01
11AX40SISO	Ant1	5755	100.00	100.00	100.00	0.00	0.01

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.
Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

11AX40SISO	Ant1	5795	100.00	100.00	100.00	0.00	0.01
11AX80SISO	Ant1	5210	100.00	100.00	100.00	0.00	0.01
11AX80SISO	Ant1	5290	100.00	100.00	100.00	0.00	0.01
11AX80SISO	Ant1	5530	100.00	100.00	100.00	0.00	0.01
11AX80SISO	Ant1	5775	100.00	100.00	100.00	0.00	0.01

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Test Graphs



NTNV-11A-Ant1-5180



NTNV-11A-Ant1-5220

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11A-Ant1-5240



NTNV-11A-Ant1-5260

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11A-Ant1-5300



NTNV-11A-Ant1-5320

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11A-Ant1-5500



NTNV-11A-Ant1-5580

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11A-Ant1-5700



NTNV-11A-Ant1-5745

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11A-Ant1-5785



NTNV-11A-Ant1-5825

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11N20SISO-Ant1-5180



NTNV-11N20SISO-Ant1-5220

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11N20SISO-Ant1-5240



NTNV-11N20SISO-Ant1-5260

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11N20SISO-Ant1-5300



NTNV-11N20SISO-Ant1-5320

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11N20SISO-Ant1-5500



NTNV-11N20SISO-Ant1-5580

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11N20SISO-Ant1-5700



NTNV-11N20SISO-Ant1-5745

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11N20SISO-Ant1-5785



NTNV-11N20SISO-Ant1-5825

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11N40SISO-Ant1-5190



NTNV-11N40SISO-Ant1-5230

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11N40SISO-Ant1-5270



NTNV-11N40SISO-Ant1-5310

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11N40SISO-Ant1-5510



NTNV-11N40SISO-Ant1-5550

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11N40SISO-Ant1-5670



NTNV-11N40SISO-Ant1-5755

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11N40SISO-Ant1-5795



NTNV-11AC20SISO-Ant1-5180

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11AC20SISO-Ant1-5220



NTNV-11AC20SISO-Ant1-5240

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11AC20SISO-Ant1-5260



NTNV-11AC20SISO-Ant1-5300

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11AC20SISO-Ant1-5320



NTNV-11AC20SISO-Ant1-5500

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11AC20SISO-Ant1-5580



NTNV-11AC20SISO-Ant1-5700

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11AC20SISO-Ant1-5745



NTNV-11AC20SISO-Ant1-5785

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11AC20SISO-Ant1-5825



NTNV-11AC40SISO-Ant1-5190

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11AC40SISO-Ant1-5230



NTNV-11AC40SISO-Ant1-5270

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11AC40SISO-Ant1-5310



NTNV-11AC40SISO-Ant1-5510

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AC40SISO-Ant1-5550



NTNV-11AC40SISO-Ant1-5670

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11AC40SISO-Ant1-5755



NTNV-11AC40SISO-Ant1-5795

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11AC80SISO-Ant1-5210



NTNV-11AC80SISO-Ant1-5290

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11AC80SISO-Ant1-5530



NTNV-11AC80SISO-Ant1-5775

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11AX20SISO-Ant1-5180



NTNV-11AX20SISO-Ant1-5220

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.



NTNV-11AX20SISO-Ant1-5240



NTNV-11AX20SISO-Ant1-5260

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AX20SISO-Ant1-5300



NTNV-11AX20SISO-Ant1-5320

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.