

September 17, 2026

Tech Mahindra (Americas) Inc.
Prashant Singh
6092 Stewart Ave
Fremont, CA 94538

Reference: EMCS142775-Photo File

Report Status Sheet

Revision	Report Date	Reason for Revision
Ø	September 17, 2026	Initial Issue.

Table of Contents

1.0	Test Photographs.....	4
-----	-----------------------	---

List of Figures

Figure 1.	FCC 15.247 & RSS-247, Antenna-Port Conducted Measurements, Test Setup.....	4
Figure 2.	FCC 15.247 & RSS-247, Radiated Spurious Emissions, (30 MHz – 1 GHz) Test Setup.....	5
Figure 3.	FCC 15.247 & RSS-247, Radiated Spurious Emissions, (30 MHz – 1 GHz) Test Setup.....	5
Figure 4.	FCC 15.247 & RSS-247, Radiated Spurious Emissions, (1 – 18 GHz) Test Setup.....	6
Figure 5.	FCC 15.247 & RSS-247, Radiated Spurious Emissions, (1 – 18 GHz) Test Setup.....	6
Figure 6.	FCC 15.247 & RSS-247, Radiated Spurious Emissions, (18 – 26 GHz) Test Setup.....	7
Figure 7.	FCC 15.247 & RSS-247, Radiated Spurious Emissions, (18 – 26 GHz) Test Setup.....	7
Figure 8.	KDB 996369, Radiated Spurious Emissions, (30 MHz – 1 GHz) Test Setup	8
Figure 9.	KDB 996369, Radiated Spurious Emissions, (30 MHz – 1 GHz) Test Setup	8
Figure 10.	KDB 996369, Radiated Spurious Emissions, (1 – 18 GHz) Test Setup	9
Figure 11.	KDB 996369, Radiated Spurious Emissions, (1 – 18 GHz) Test Setup	9
Figure 12.	KDB 996369, Radiated Spurious Emissions, (18 – 20 GHz) Test Setup	10
Figure 13.	KDB 996369, Radiated Spurious Emissions, (18 – 20 GHz) Test Setup	10

1.0 Test Photographs

WIRS142775-FCC 15.247_RSS-247




Figure 1. FCC 15.247 & RSS-247, Antenna-Port Conducted Measurements, Test Setup




Figure 2. FCC 15.247 & RSS-247, Radiated Spurious Emissions, (30 MHz – 1 GHz) Test Setup




Figure 3. FCC 15.247 & RSS-247, Radiated Spurious Emissions, (30 MHz – 1 GHz) Test Setup




Figure 4. FCC 15.247 & RSS-247, Radiated Spurious Emissions, (1 – 18 GHz) Test Setup




Figure 5. FCC 15.247 & RSS-247, Radiated Spurious Emissions, (1 – 18 GHz) Test Setup




Figure 6. FCC 15.247 & RSS-247, Radiated Spurious Emissions, (18 – 26 GHz) Test Setup




Figure 7. FCC 15.247 & RSS-247, Radiated Spurious Emissions, (18 – 26 GHz) Test Setup

WIRS142775-KDB 996369 D04 V.02




Figure 8. KDB 996369, Radiated Spurious Emissions, (30 MHz – 1 GHz) Test Setup




Figure 9. KDB 996369, Radiated Spurious Emissions, (30 MHz – 1 GHz) Test Setup




Figure 10. KDB 996369, Radiated Spurious Emissions, (1 – 18 GHz) Test Setup




Figure 11. KDB 996369, Radiated Spurious Emissions, (1 – 18 GHz) Test Setup




Figure 12. KDB 996369, Radiated Spurious Emissions, (18 – 20 GHz) Test Setup




Figure 13. KDB 996369, Radiated Spurious Emissions, (18 – 20 GHz) Test Setup

END OF REPORT