





Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Appendix E: Band edge measurements

Test Result B1/2/3

Test Mode	Antenna	ChName	Frequency[MHz]	Result[dBm]	Limit[dBm]	Verdict
11A	Ant1	Low	5180	-44.94	≤-27	PASS
11A	Ant1	High	5320	-44.84	≤-27	PASS
11A	Ant1	Low	5500	-31.82	≤-27	PASS
11A	Ant1	High	5700	-32.5	≤-27	PASS
11N20SISO	Ant1	Low	5180	-43.81	≤-27	PASS
11N20SISO	Ant1	High	5320	-43.64	≤-27	PASS
11N20SISO	Ant1	Low	5500	-33.79	≤-27	PASS
11N20SISO	Ant1	High	5700	-37.99	≤-27	PASS
11N40SISO	Ant1	Low	5190	-38.61	≤-27	PASS
11N40SISO	Ant1	High	5310	-42.74	≤-27	PASS
11N40SISO	Ant1	Low	5510	-34.32	≤-27	PASS
11N40SISO	Ant1	High	5670	-44.27	≤-27	PASS
11AC20SISO	Ant1	Low	5180	-42.93	≤-27	PASS
11AC20SISO	Ant1	High	5320	-42.68	≤-27	PASS
11AC20SISO	Ant1	Low	5500	-33.67	≤-27	PASS
11AC20SISO	Ant1	High	5700	-38.02	≤-27	PASS
11AC40SISO	Ant1	Low	5190	-41.65	≤-27	PASS
11AC40SISO	Ant1	High	5310	-37.09	≤-27	PASS
11AC40SISO	Ant1	Low	5510	-31.24	≤-27	PASS
11AC40SISO	Ant1	High	5670	-40.85	≤-27	PASS

Note: The margin plus the antenna gain also meets the limit.

Test Result B4

Test Mode	Antenna	Ch. Name	Frequency[MHz]	FreqRange [MHz]	Result [dBm]	Limit [dBm]	Verdict
11A	Ant1	Low	5745	5720~5725	-38.8	≤16.08	PASS
11A	Ant1	Low	5745	5700~5720	-44.85	≤10.41	PASS
11A	Ant1	Low	5745	5650~5700	-48.18	≤-26.96	PASS
11A	Ant1	Low	5745	5760~5650	-46.45	≤-27	PASS
11A	Ant1	High	5825	5850~5855	-42.34	≤17.57	PASS
11A	Ant1	High	5825	5855~5875	-45.19	≤10.55	PASS
11A	Ant1	High	5825	5875~5925	-46.35	≤-26.11	PASS
11A	Ant1	High	5825	5925~5935	-47.55	≤-27	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

11N20SI SO	Ant1	Low	5745	5720~5725	-33.12	≤20.80	PASS
11N20SI SO	Ant1	Low	5745	5700~5720	-43.63	≤10.47	PASS
11N20SI SO	Ant1	Low	5745	5650~5700	-48.83	≤-26.70	PASS
11N20SI SO	Ant1	Low	5745	5760~5650	-47.39	≤-27	PASS
11N20SI SO	Ant1	High	5825	5850~5855	-42.63	≤15.73	PASS
11N20SI SO	Ant1	High	5825	5855~5875	-43.11	≤11.08	PASS
11N20SI SO	Ant1	High	5825	5875~5925	-48.49	≤-26.71	PASS
11N20SI SO	Ant1	High	5825	5925~5935	-46.73	≤-27	PASS
11N40SI SO	Ant1	Low	5755	5720~5725	-34.09	≤16.66	PASS
11N40SI SO	Ant1	Low	5755	5700~5720	-34.31	≤15.24	PASS
11N40SI SO	Ant1	Low	5755	5650~5700	-46.85	≤-26.80	PASS
11N40SI SO	Ant1	Low	5755	5780~5650	-46.69	≤-27	PASS
11N40SI SO	Ant1	High	5795	5850~5855	-45.43	≤15.66	PASS
11N40SI SO	Ant1	High	5795	5855~5875	-46.65	≤10.11	PASS
11N40SI SO	Ant1	High	5795	5875~5925	-47.54	≤-26.95	PASS
11N40SI SO	Ant1	High	5795	5925~5935	-46.06	≤-27	PASS
11AC20S ISO	Ant1	Low	5745	5720~5725	-38.84	≤15.82	PASS
11AC20S ISO	Ant1	Low	5745	5700~5720	-41.23	≤11.73	PASS
11AC20S ISO	Ant1	Low	5745	5650~5700	-47.26	≤-26.87	PASS
11AC20S ISO	Ant1	Low	5745	5760~5650	-47.08	≤-27	PASS
11AC20S ISO	Ant1	High	5825	5850~5855	-43.14	≤16.34	PASS
11AC20S	Ant1	High	5825	5855~5875	-45.09	≤10.78	PASS

Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

ISO							
11AC20S ISO	Ant1	High	5825	5875~5925	-46.46	≤ -26.31	PASS
11AC20S ISO	Ant1	High	5825	5925~5935	-45.8	≤ -27	PASS
11AC40S ISO	Ant1	Low	5755	5720~5725	-33.43	≤ 18.51	PASS
11AC40S ISO	Ant1	Low	5755	5700~5720	-34.23	≤ 15.39	PASS
11AC40S ISO	Ant1	Low	5755	5650~5700	-47.38	≤ -26.90	PASS
11AC40S ISO	Ant1	Low	5755	5780~5650	-46.34	≤ -27	PASS
11AC40S ISO	Ant1	High	5795	5850~5855	-44.64	≤ 16.03	PASS
11AC40S ISO	Ant1	High	5795	5855~5875	-46.69	≤ 10.66	PASS
11AC40S ISO	Ant1	High	5795	5875~5925	-47.13	≤ -26.83	PASS
11AC40S ISO	Ant1	High	5795	5925~5935	-47.19	≤ -27	PASS

Note: The margin plus the antenna gain also meets the limit.

Test Graphs B1/2/3




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com








Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com











Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com







Test Graphs B4



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com