


Equipment Photographs



GS1005

(Internal)





Equipment Photographs

(Internal)



Equipment Photographs

(Internal)



Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: HK21120398


Equipment Photographs

(Internal)





Equipment Photographs

(Internal)





Equipment Photographs

(Internal)



Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: HK21120398



Equipment Photographs

(Internal)





Equipment Photographs

(Internal)





Equipment Photographs

(Internal)





Equipment Photographs

(Internal)



Equipment Photographs

(Internal)



INTERTEK TESTING SERVICE

Report No.: HK21120398

Equipment Photographs

(Internal)

