



Please refer to following plots:




Date: 19.JAN.2021 09:09:17




Date: 1.JAN.2021 17:28:50

Band 2_1.4 MHz_L_QPSK_RB6#0




Date: 19.JAN.2021 09:13:25

Band 2_1.4 MHz_H_16QAM_RB6#0




Date: 19.JAN.2021 09:10:42

Band 2_1.4 MHz_Middle_16QAM_RB6#0




Date: 1.JAN.2021 17:29:10

Band 2_1.4 MHz_L_16QAM_RB6#0




Date: 19.JAN.2021 09:12:34

Band 2_3 MHz_H_QPSK_RB15#0




Date: 19.JAN.2021 09:26:55

Band 2_3 MHz_Middle_QPSK_RB15#0




Date: 1.JAN.2021 17:29:32

Band 2_3 MHz_L_QPSK_RB15#0




Date: 19.JAN.2021 09:20:21

Band 2_3 MHz_H_16QAM_RB15#0




Date: 19.JAN.2021 09:25:31

Band 2_3 MHz_Middle_16QAM_RB15#0




Date: 1.JAN.2021 17:29:48

Band 2_3 MHz_L_16QAM_RB15#0




Date: 19.JAN.2021 09:22:00

Band 2_5 MHz_H_QPSK_RB25#0




Date: 19.JAN.2021 09:32:36

Band 2_5 MHz_Middle_QPSK_RB25#0




Date: 1.JAN.2021 17:30:12

Band 2_5 MHz_L_QPSK_RB25#0




Date: 19.JAN.2021 09:37:02

Band 2_5 MHz_H_16QAM_RB25#0




Date: 19.JAN.2021 09:34:37

Band 2_5 MHz_Middle_16QAM_RB25#0




Date: 1.JAN.2021 17:30:32

Band 2_5 MHz_L_16QAM_RB25#0




Date: 19.JAN.2021 09:36:19

Band 2_10 MHz_H_QPSK_RB50#0




Date: 19.JAN.2021 16:40:43

Band 2_10 MHz_Middle_QPSK_RB50#0




Date: 1.JAN.2021 17:30:55

Band 2_10 MHz_L_QPSK_RB50#0




Date: 19.JAN.2021 09:39:09

Band 2_10 MHz_H_16QAM_RB50#0




Date: 19.JAN.2021 16:02:51

Band 2_10 MHz_Middle_16QAM_RB50#0




Date: 1.JAN.2021 17:31:12

Band 2_10 MHz_L_16QAM_RB50#0




Date: 19.JAN.2021 09:40:36

Band 2_15 MHz_H_QPSK_RB75#0




Date: 19.JAN.2021 16:43:15

Band 2_15 MHz_Middle_QPSK_RB75#0




Date: 1.JAN.2021 17:31:40

Band 2_15 MHz_L_QPSK_RB75#0




Date: 19.JAN.2021 16:46:41

Band 2_15 MHz_H_16QAM_RB75#0




Date: 19.JAN.2021 16:44:25

Band 2_15 MHz_Middle_16QAM_RB75#0




Date: 1.JAN.2021 17:32:06

Band 2_15 MHz_L_16QAM_RB75#0




Date: 19.JAN.2021 16:45:39

Band 2_20 MHz_H_QPSK_RB100#0




Date: 19.JAN.2021 16:54:20

Band 2_20 MHz_Middle_QPSK_RB100#0




Date: 1.JAN.2021 17:32:34

Band 2_20 MHz_L_QPSK_RB100#0




Date: 19.JAN.2021 16:48:34

Band 2_20 MHz_H_16QAM_RB100#0




Date: 19.JAN.2021 16:52:20

Band 2_20 MHz_Middle_16QAM_RB100#0




Date: 1.JAN.2021 17:33:00

Band 2_20 MHz_L_16QAM_RB100#0




Date: 19.JAN.2021 16:50:21

Band 4_1.4 MHz_H_QPSK_RB6#0




Date: 19.JAN.2021 17:28:38

Band 4_1.4 MHz_Middle_QPSK_RB6#0




Date: 1.JAN.2021 17:33:22

Band 4_1.4 MHz_L_QPSK_RB6#0




Date: 19.JAN.2021 17:33:09

Band 4_1.4 MHz_H_16QAM_RB6#0




Date: 19.JAN.2021 17:30:41

Band 4_1.4 MHz_Middle_16QAM_RB6#0




Date: 1.JAN.2021 17:33:44

Band 4_1.4 MHz_L_16QAM_RB6#0




Date: 19.JAN.2021 17:32:11

Band 4_3 MHz_H_QPSK_RB15#0




Date: 19.JAN.2021 17:38:05

Band 4_3 MHz_Middle_QPSK_RB15#0




Date: 1.JAN.2021 17:34:06

Band 4_3 MHz_L_QPSK_RB15#0




Date: 19.JAN.2021 17:34:39

Band 4_3 MHz_H_16QAM_RB15#0




Date: 19.JAN.2021 17:37:20

Band 4_3 MHz_Middle_16QAM_RB15#0




Date: 1.JAN.2021 17:34:25

Band 4_3 MHz_L_16QAM_RB15#0




Date: 19.JAN.2021 17:35:42

Band 4_5 MHz_H_QPSK_RB25#0




Date: 19.JAN.2021 17:44:53

Band 4_5 MHz_Middle_QPSK_RB25#0




Date: 1.JAN.2021 17:34:50

Band 4_5 MHz_L_QPSK_RB25#0




Date: 19.JAN.2021 17:43:50

Band 4_5 MHz_H_16QAM_RB25#0




Date: 19.JAN.2021 17:45:34

Band 4_5 MHz_Middle_16QAM_RB25#0




Date: 1.JAN.2021 17:35:16

Band 4_5 MHz_L_16QAM_RB25#0




Date: 19.JAN.2021 17:40:12

Band 4_10 MHz_H_QPSK_RB50#0




Date: 19.JAN.2021 18:07:06

Band 4_10 MHz_Middle_QPSK_RB50#0




Date: 1.JAN.2021 17:35:36

Band 4_10 MHz_L_QPSK_RB50#0




Date: 19.JAN.2021 17:49:51

Band 4_10 MHz_H_16QAM_RB50#0




Date: 19.JAN.2021 18:08:40

Band 4_10 MHz_Middle_16QAM_RB50#0




Date: 1.JAN.2021 17:35:53

Band 4_10 MHz_L_16QAM_RB50#0




Date: 19.JAN.2021 18:02:49

Band 4_15 MHz_H_QPSK_RB75#0





Date: 19.JAN.2021 18:14:00


Band 4_15 MHz_Middle_QPSK_RB75#0



Date: 1.JAN.2021 17:36:24




Band 4_15 MHz_Middle_16QAM_RB75#0




Date: 1.JAN.2021 17:36:50

Band 4_15 MHz_L_16QAM_RB75#0




Date: 19.JAN.2021 18:11:22

Band 4_20 MHz_H_QPSK_RB100#0




Date: 19.JAN.2021 18:21:51

Band 4_20 MHz_Middle_QPSK_RB100#0




Date: 1.JAN.2021 17:37:21

Band 4_20 MHz_L_QPSK_RB100#0




Date: 19.JAN.2021 18:18:51

Band 4_20 MHz_H_16QAM_RB100#0




Date: 19.JAN.2021 18:21:03

Band 4_20 MHz_Middle_16QAM_RB100#0




Date: 1.JAN.2021 17:37:44

Band 4_20 MHz_L_16QAM_RB100#0




Date: 19.JAN.2021 18:19:43

Band 5_1.4 MHz_H_QPSK_RB6#0




Date: 19.JAN.2021 18:29:14

Band 5_1.4 MHz_Middle_QPSK_RB6#0




Date: 1.JAN.2021 17:38:12

Band 5_1.4 MHz_L_QPSK_RB6#0




Date: 19.JAN.2021 18:26:22

Band 5_1.4 MHz_H_16QAM_RB6#0




Date: 19.JAN.2021 18:28:32

Band 5_1.4 MHz_Middle_16QAM_RB6#0




Date: 1.JAN.2021 17:38:32

Band 5_1.4 MHz_L_16QAM_RB6#0




Date: 19.JAN.2021 18:27:24

Band 5_3 MHz_H_QPSK_RB15#0




Date: 19.JAN.2021 18:35:13

Band 5_3 MHz_Middle_QPSK_RB15#0




Date: 1.JAN.2021 17:38:53

Band 5_3 MHz_L_QPSK_RB15#0




Date: 19.JAN.2021 18:31:03

Band 5_3 MHz_H_16QAM_RB15#0




Date: 19.JAN.2021 18:34:24

Band 5_3 MHz_Middle_16QAM_RB15#0




Date: 1.JAN.2021 17:39:09

Band 5_3 MHz_L_16QAM_RB15#0




Date: 19.JAN.2021 18:31:59

Band 5_5 MHz_H_QPSK_RB25#0




Date: 19.JAN.2021 19:03:12

Band 5_5 MHz_Middle_QPSK_RB25#0




Date: 1.JAN.2021 17:39:40

Band 5_5 MHz_L_QPSK_RB25#0




Date: 19.JAN.2021 18:58:21

Band 5_5 MHz_H_16QAM_RB25#0




Date: 19.JAN.2021 19:01:51

Band 5_5 MHz_Middle_16QAM_RB25#0




Date: 1.JAN.2021 17:40:03

Band 5_5 MHz_L_16QAM_RB25#0




Date: 19.JAN.2021 19:00:26

Band 5_10 MHz_H_QPSK_RB50#0




Date: 19.JAN.2021 19:09:44

Band 5_10 MHz_Middle_QPSK_RB50#0




Date: 1.JAN.2021 17:40:25

Band 5_10 MHz_L_QPSK_RB50#0




Date: 19.JAN.2021 19:06:36

Band 5_10 MHz_H_16QAM_RB50#0




Date: 19.JAN.2021 19:08:41

Band 5_10 MHz_Middle_16QAM_RB50#0




Date: 1.JAN.2021 17:40:46

Band 5_10 MHz_L_16QAM_RB50#0




Date: 19.JAN.2021 19:05:14

Band 7_5 MHz_H_QPSK_RB25#0




Date: 20.JAN.2021 10:36:38

Band 7_5 MHz_Middle_QPSK_RB25#0




Date: 20.JAN.2021 08:47:38

Band 7_5 MHz_L_QPSK_RB25#0




Date: 20.JAN.2021 10:31:55

Band 7_5 MHz_H_16QAM_RB25#0




Date: 20.JAN.2021 10:35:43

Band 7_5 MHz_Middle_16QAM_RB25#0




Date: 20.JAN.2021 08:48:05

Band 7_5 MHz_L_16QAM_RB25#0




Date: 20.JAN.2021 10:34:04

Band 7_10 MHz_H_QPSK_RB50#0




Date: 20.JAN.2021 10:43:08

Band 7_10 MHz_Middle_QPSK_RB50#0




Date: 20.JAN.2021 08:48:29

Band 7_10 MHz_I_QPSK_RB50#0




Date: 20.JAN.2021 10:39:12

Band 7_10 MHz_H_16QAM_RB50#0




Date: 20.JAN.2021 10:42:07

Band 7_10 MHz_Middle_16QAM_RB50#0




Date: 20.JAN.2021 08:48:49

Band 7_10 MHz_L_16QAM_RB50#0




Date: 20.JAN.2021 10:40:35

Band 7_15 MHz_H_QPSK_RB75#0




Date: 20.JAN.2021 11:03:48

Band 7_15 MHz_Middle_QPSK_RB75#0




Date: 20.JAN.2021 08:49:20

Band 7_15 MHz_L_QPSK_RB75#0




Date: 20.JAN.2021 10:51:09

Band 7_15 MHz_H_16QAM_RB75#0




Date: 20.JAN.2021 11:02:35

Band 7_15 MHz_Middle_16QAM_RB75#0




Date: 20.JAN.2021 08:49:47

Band 7_15 MHz_L_16QAM_RB75#0




Date: 20.JAN.2021 10:52:00

Band 7_20 MHz_H_QPSK_RB100#0




Date: 20.JAN.2021 11:09:46

Band 7_20 MHz_Middle_QPSK_RB100#0




Date: 20.JAN.2021 08:50:13

Band 7_20 MHz_L_QPSK_RB100#0




Date: 20.JAN.2021 11:06:21

Band 7_20 MHz_H_16QAM_RB100#0




Date: 20.JAN.2021 11:08:58

Band 7_20 MHz_Middle_16QAM_RB100#0




Date: 20.JAN.2021 08:50:41

Band 7_20 MHz_L_16QAM_RB100#0




Date: 20.JAN.2021 11:07:39

Band 17_5 MHz_H_QPSK_RB25#0




Date: 19.JAN.2021 18:51:50

Band 17_5 MHz_Middle_QPSK_RB25#0




Date: 1.JAN.2021 17:41:14

Band 17_5 MHz_L_QPSK_RB25#0




Date: 19.JAN.2021 18:47:29


Band 17_5 MHz_H_16QAM_RB25#0




Date: 19.JAN.2021 18:50:49




Date: 1.JAN.2021 17:41:37



Date: 19.JAN.2021 18:48:23




Date: 19.JAN.2021 18:55:50




Date: 1.JAN.2021 17:42:06

Band 17_10 MHz_L_QPSK_RB50#0




Date: 19.JAN.2021 18:54:28

Band 17_10 MHz_H_16QAM_RB50#0




Date: 19.JAN.2021 18:56:37

Band 17_10 MHz_Middle_16QAM_RB50#0



Date: 1.JAN.2021 17:42:26

Band 17_10 MHz_L_16QAM_RB50#0



Date: 19.JAN.2021 18:53:17