

Appendix C – SAR Test Setup Photos



Test Position Back 0 mm Gap

Note: The cable is removed for testing.



Test Position Back (Front View) 0 mm Gap



Test Position Front 0 mm Gap

Note: The cable is removed for testing.




Test Position Left 0 mm Gap

Note: The cable is removed for testing.



Test Position Right 0 mm Gap

Note: The cable is removed for testing.



Test Position Top 47 mm Gap

Note: The cable is removed for testing.



Test Position Bottom 0 mm Gap



Front of Device



Back of Device