




20MHz_Low_QPSK_1@0(30MHz~1GHz)




20MHz_Low_QPSK_1@0(1GHz~15GHz)




20MHz_Low_QPSK_1@0(15GHz~17.2GHz)




20MHz_Low_QPSK_100@0(30MHz~1GHz)




20MHz_Low_QPSK_100@0(1GHz~15GHz)



20MHz_Low_QPSK_100@0(15GHz~17.2GHz)




20MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
 Date: 6.SEP.2026 00:19:01

20MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
 Date: 6.SEP.2026 00:19:09

20MHz_Middle_QPSK_1@0(15GHz~17.325GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
 Date: 6.SEP.2026 00:19:15

20MHz_Middle_QPSK_100@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
 Date: 6.SEP.2026 00:19:27

20MHz_Middle_QPSK_100@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
 Date: 6.SEP.2026 00:19:36

20MHz_Middle_QPSK_100@0(15GHz~17.325GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
 Date: 6.SEP.2026 00:19:43

20MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:19:54

20MHz_High_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:20:02

20MHz_High_QPSK_1@0(15GHz~17.45GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:20:09

20MHz_High_QPSK_100@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:20:20

20MHz_High_QPSK_100@0(1GHz~15GHz)



ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:20:28

20MHz_High_QPSK_100@0(15GHz~17.45GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:20:34


LTE Band 66, Normal

1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~1GHz)




1.4MHz_Low_QPSK_1@0(1GHz~15GHz)




1.4MHz_Low_QPSK_1@0(15GHz~17.107GHz)




1.4MHz_Low_QPSK_6@0(30MHz~1GHz)




1.4MHz_Low_QPSK_6@0(1GHz~15GHz)



1.4MHz_Low_QPSK_6@0(15GHz~17.107GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:32:26

1.4MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:32:34

1.4MHz_Middle_QPSK_1@0(15GHz~17.45GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:32:40

1.4MHz_Middle_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:32:52

1.4MHz_Middle_QPSK_6@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:33:00

1.4MHz_Middle_QPSK_6@0(15GHz~17.45GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:33:06

1.4MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:33:18

1.4MHz_High_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:33:26

1.4MHz_High_QPSK_1@0(15GHz~17.793GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:33:32

1.4MHz_High_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:33:44

1.4MHz_High_QPSK_6@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:33:52

1.4MHz_High_QPSK_6@0(15GHz~17.793GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:33:58

3MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:34:14

3MHz_Low_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:34:23

3MHz_Low_QPSK_1@0(15GHz~17.115GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:34:29

3MHz_Low_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:34:41

3MHz_Low_QPSK_15@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:34:48

3MHz_Low_QPSK_15@0(15GHz~17.115GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:34:55


3MHz_Middle_QPSK_1@0(30MHz~1GHz)




3MHz_Middle_QPSK_1@0(1GHz~15GHz)




3MHz_Middle_QPSK_1@0(15GHz~17.45GHz)




3MHz_Middle_QPSK_15@0(30MHz~1GHz)




3MHz_Middle_QPSK_15@0(1GHz~15GHz)




3MHz_Middle_QPSK_15@0(15GHz~17.45GHz)




3MHz_High_QPSK_1@0(30MHz~1GHz)




3MHz_High_QPSK_1@0(1GHz~15GHz)




3MHz_High_QPSK_1@0(15GHz~17.785GHz)




3MHz_High_QPSK_15@0(30MHz~1GHz)




3MHz_High_QPSK_15@0(1GHz~15GHz)




3MHz_High_QPSK_15@0(15GHz~17.785GHz)




5MHz_Low_QPSK_1@0(30MHz~1GHz)




5MHz_Low_QPSK_1@0(1GHz~15GHz)




5MHz_Low_QPSK_1@0(15GHz~17.125GHz)




5MHz_Low_QPSK_25@0(30MHz~1GHz)




5MHz_Low_QPSK_25@0(1GHz~15GHz)




5MHz_Low_QPSK_25@0(15GHz~17.125GHz)




5MHz_Middle_QPSK_1@0(30MHz~1GHz)




5MHz_Middle_QPSK_1@0(1GHz~15GHz)




5MHz_Middle_QPSK_1@0(15GHz~17.45GHz)




5MHz_Middle_QPSK_25@0(30MHz~1GHz)




5MHz_Middle_QPSK_25@0(1GHz~15GHz)




5MHz_Middle_QPSK_25@0(15GHz~17.45GHz)




5MHz_High_QPSK_1@0(30MHz~1GHz)




5MHz_High_QPSK_1@0(1GHz~15GHz)




5MHz_High_QPSK_1@0(15GHz~17.775GHz)




5MHz_High_QPSK_25@0(30MHz~1GHz)




5MHz_High_QPSK_25@0(1GHz~15GHz)



5MHz_High_QPSK_25@0(15GHz~17.775GHz)




10MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:39:33

10MHz_Low_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:39:41

10MHz_Low_QPSK_1@0(15GHz~17.15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:39:48

10MHz_Low_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:39:59

10MHz_Low_QPSK_50@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:40:07

10MHz_Low_QPSK_50@0(15GHz~17.15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:40:13

10MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:40:25

10MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:40:33

10MHz_Middle_QPSK_1@0(15GHz~17.45GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:40:40

10MHz_Middle_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:40:53

10MHz_Middle_QPSK_50@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:41:01

10MHz_Middle_QPSK_50@0(15GHz~17.45GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:41:07

10MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:41:18

10MHz_High_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:41:26

10MHz_High_QPSK_1@0(15GHz~17.75GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:41:33

10MHz_High_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:41:45

10MHz_High_QPSK_50@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:41:53

10MHz_High_QPSK_50@0(15GHz~17.75GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:41:59

15MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:45:52

15MHz_Low_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:46:00

15MHz_Low_QPSK_1@0(15GHz~17.175GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:46:06

15MHz_Low_QPSK_75@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:46:18

15MHz_Low_QPSK_75@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:46:26

15MHz_Low_QPSK_75@0(15GHz~17.175GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:46:32

15MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
 Date: 6.SEP.2026 00:46:44

15MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
 Date: 6.SEP.2026 00:46:51

15MHz_Middle_QPSK_1@0(15GHz~17.45GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
 Date: 6.SEP.2026 00:46:58

15MHz_Middle_QPSK_75@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
 Date: 6.SEP.2026 00:47:09

15MHz_Middle_QPSK_75@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
 Date: 6.SEP.2026 00:47:17

15MHz_Middle_QPSK_75@0(15GHz~17.45GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
 Date: 6.SEP.2026 00:47:24

15MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:47:35

15MHz_High_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:47:43

15MHz_High_QPSK_1@0(15GHz~17.725GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:47:50

15MHz_High_QPSK_75@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:48:01

15MHz_High_QPSK_75@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:48:09

15MHz_High_QPSK_75@0(15GHz~17.725GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:48:15


20MHz_Low_QPSK_1@0(30MHz~1GHz)




20MHz_Low_QPSK_1@0(1GHz~15GHz)




20MHz_Low_QPSK_1@0(15GHz~17.2GHz)




20MHz_Low_QPSK_100@0(30MHz~1GHz)




20MHz_Low_QPSK_100@0(1GHz~15GHz)



20MHz_Low_QPSK_100@0(15GHz~17.2GHz)




20MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:49:23

20MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:49:31

20MHz_Middle_QPSK_1@0(15GHz~17.45GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:49:38

20MHz_Middle_QPSK_100@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:49:50

20MHz_Middle_QPSK_100@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:49:58

20MHz_Middle_QPSK_100@0(15GHz~17.45GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:50:05

20MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:50:17

20MHz_High_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:50:24

20MHz_High_QPSK_1@0(15GHz~17.7GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:50:32

20MHz_High_QPSK_100@0(30MHz~1GHz)




ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:50:43

20MHz_High_QPSK_100@0(1GHz~15GHz)



ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:50:51

20MHz_High_QPSK_100@0(15GHz~17.7GHz)



ProjectNo.:2604W76366E-RF Tester:Allen Qin
Date: 6.SEP.2026 00:50:58

***** END *****