







11AC20MIMO_Ant1_5745




11AC20MIMO_Ant2_5745




11AC20MIMO_Ant1_5785




11AC20MIMO_Ant2_5785



11AC20MIMO_Ant1_5825




11AC20MIMO_Ant2_5825




Date: 14.AUG.2023 18:17:05

11AC40MIMO_Ant1_5190




Date: 15.AUG.2023 19:32:53

11AC40MIMO_Ant2_5190




Date: 15.AUG.2023 19:36:10


11AC40MIMO_Ant1_5230




11AC40MIMO_Ant2_5230




11AC40MIMO_Ant1_5270




11AC40MIMO_Ant2_5270




11AC40MIMO_Ant1_5310




11AC40MIMO_Ant2_5310




11AC40MIMO_Ant1_5510




11AC40MIMO_Ant2_5510



11AC40MIMO_Ant1_5550




11AC40MIMO_Ant2_5550




Date: 16.AUG.2023 10:38:28

11AC40MIMO_Ant1_5670




Date: 16.AUG.2023 10:42:40

11AC40MIMO_Ant2_5670




Date: 16.AUG.2023 10:45:37


11AC40MIMO_Ant1_5755




11AC40MIMO_Ant2_5755



11AC40MIMO_Ant1_5795




11AC40MIMO_Ant2_5795




Date: 16.AUG.2023 11:19:35

11AC80MIMO_Ant1_5210




Date: 16.AUG.2023 11:23:43

11AC80MIMO_Ant2_5210




Date: 16.AUG.2023 11:32:10


11AC80MIMO_Ant1_5290




11AC80MIMO_Ant2_5290




11AC80MIMO_Ant1_5530




11AC80MIMO_Ant2_5530




11AC80MIMO_Ant1_5610




11AC80MIMO_Ant2_5610



11AC80MIMO_Ant1_5775



11AC80MIMO_Ant2_5775



-----End of the report-----