







11N20SISO_Ant1_5500




11N20SISO_Ant1_5580




11N20SISO_Ant1_5700




11N20SISO_Ant1_5745



11N20SISO_Ant1_5785




11N20SISO_Ant1_5825




Date: 17.AUG.2023 11:23:56

11N40SISO_Ant1_5190




Date: 17.AUG.2023 11:49:56

11N40SISO_Ant1_5230




Date: 17.AUG.2023 11:56:19

11N40SISO_Ant1_5270




Date: 17.AUG.2023 14:19:54

11N40SISO_Ant1_5310




Date: 17.AUG.2023 14:22:08

11N40SISO_Ant1_5510




Date: 17.AUG.2023 14:29:48

11N40SISO_Ant1_5550




Date: 17.AUG.2023 14:33:33

11N40SISO_Ant1_5670




Date: 17.AUG.2023 14:35:55

11N40SISO_Ant1_5755




Date: 17.AUG.2023 14:39:42


11N40SISO_Ant1_5795




11AC20SISO_Ant1_5180



11AC20SISO_Ant1_5200




11AC20SISO_Ant1_5240




Date: 17.AUG.2023 14:58:24

11AC20SISO_Ant1_5260




Date: 17.AUG.2023 15:00:45

11AC20SISO_Ant1_5280




Date: 17.AUG.2023 15:03:05

11AC20SISO_Ant1_5320




Date: 17.AUG.2023 15:09:53

11AC20SISO_Ant1_5500




Date: 17.AUG.2023 15:13:39

11AC20SISO_Ant1_5580




Date: 17.AUG.2023 15:17:13

11AC20SISO_Ant1_5700




Date: 17.AUG.2023 15:19:42

11AC20SISO_Ant1_5745




Date: 17.AUG.2023 15:26:32

11AC20SISO_Ant1_5785




Date: 17.AUG.2023 15:31:18

11AC20SISO_Ant1_5825




Date: 17.AUG.2023 15:33:28

11AC40SISO_Ant1_5190




Date: 17.AUG.2023 15:37:24

11AC40SISO_Ant1_5230




Date: 17.AUG.2023 15:59:57


11AC40SISO_Ant1_5270




11AC40SISO_Ant1_5310




11AC40SISO_Ant1_5510




11AC40SISO_Ant1_5550




11AC40SISO_Ant1_5670




11AC40SISO_Ant1_5755




11AC40SISO_Ant1_5795




11AC80SISO_Ant1_5210




11AC80SISO_Ant1_5290




11AC80SISO_Ant1_5530



11AC80SISO_Ant1_5610



11AC80SISO_Ant1_5775



-----End of the report-----