

SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=15MHz Channel=647168 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=15MHz Channel=647168 RB=36@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=15MHz Channel=656000 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=15MHz Channel=656000 RB=36@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=15MHz Channel=664832 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=15MHz Channel=664832 RB=36@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=20MHz Channel=647334 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=20MHz Channel=647334 RB=50@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=20MHz Channel=656000 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=20MHz Channel=656000 RB=50@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=20MHz Channel=664666 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=20MHz Channel=664666 RB=50@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=30MHz Channel=647668 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=30MHz Channel=647668 RB=75@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=30MHz Channel=656000 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=30MHz Channel=656000 RB=75@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=30MHz Channel=664332 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=30MHz Channel=664332 RB=75@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=40MHz Channel=648000 RB=100@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=40MHz Channel=648000 RB=1@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=40MHz Channel=656000 RB=100@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=40MHz Channel=656000 RB=1@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=40MHz Channel=664000 RB=100@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=40MHz Channel=664000 RB=1@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=50MHz Channel=648334 RB=128@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=50MHz Channel=648334 RB=1@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=50MHz Channel=656000 RB=128@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=50MHz Channel=656000 RB=1@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=50MHz Channel=663666 RB=128@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=50MHz Channel=663666 RB=1@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=60MHz Channel=648668 RB=162@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=60MHz Channel=648668 RB=1@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=60MHz Channel=656000 RB=162@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=60MHz Channel=656000 RB=1@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=60MHz Channel=663332 RB=162@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=60MHz Channel=663332 RB=1@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=80MHz Channel=649334 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=80MHz Channel=649334 RB=216@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=80MHz Channel=656000 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=80MHz Channel=656000 RB=216@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=80MHz Channel=662666 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=80MHz Channel=662666 RB=216@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=90MHz Channel=649668 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=90MHz Channel=649668 RB=240@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=90MHz Channel=656000 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=90MHz Channel=656000 RB=240@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=90MHz Channel=662332 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_16QAM BW=90MHz Channel=662332 RB=240@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=100MHz Channel=650000 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=100MHz Channel=650000 RB=270@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=100MHz Channel=656000 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=100MHz Channel=656000 RB=270@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.

SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=100MHz Channel=662000 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=100MHz Channel=662000 RB=270@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=10MHz Channel=647000 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=10MHz Channel=647000 RB=24@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=10MHz Channel=656000 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=10MHz Channel=656000 RB=24@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=10MHz Channel=665000 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=10MHz Channel=665000 RB=24@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=15MHz Channel=647168 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=15MHz Channel=647168 RB=36@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=15MHz Channel=656000 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=15MHz Channel=656000 RB=36@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=15MHz Channel=664832 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=15MHz Channel=664832 RB=36@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=20MHz Channel=647334 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=20MHz Channel=647334 RB=50@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=20MHz Channel=656000 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=20MHz Channel=656000 RB=50@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=20MHz Channel=664666 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=20MHz Channel=664666 RB=50@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=30MHz Channel=647668 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=30MHz Channel=647668 RB=75@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=30MHz Channel=656000 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=30MHz Channel=656000 RB=75@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=30MHz Channel=664332 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=30MHz Channel=664332 RB=75@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=40MHz Channel=648000 RB=100@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=40MHz Channel=648000 RB=1@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=40MHz Channel=656000 RB=100@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=40MHz Channel=656000 RB=1@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=40MHz Channel=664000 RB=100@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=40MHz Channel=664000 RB=1@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=50MHz Channel=648334 RB=128@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=50MHz Channel=648334 RB=1@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=50MHz Channel=656000 RB=128@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=50MHz Channel=656000 RB=1@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=50MHz Channel=663666 RB=128@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=50MHz Channel=663666 RB=1@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=60MHz Channel=648668 RB=162@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=60MHz Channel=648668 RB=1@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=60MHz Channel=656000 RB=162@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=60MHz Channel=656000 RB=1@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=60MHz Channel=663332 RB=162@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=60MHz Channel=663332 RB=1@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=80MHz Channel=649334 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=80MHz Channel=649334 RB=216@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=80MHz Channel=656000 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=80MHz Channel=656000 RB=216@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=80MHz Channel=662666 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=80MHz Channel=662666 RB=216@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=90MHz Channel=649668 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=90MHz Channel=649668 RB=240@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=90MHz Channel=656000 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=90MHz Channel=656000 RB=240@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=90MHz Channel=662332 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_256QAM BW=90MHz Channel=662332 RB=240@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_64QAM BW=100MHz Channel=650000 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_64QAM BW=100MHz Channel=650000 RB=270@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_64QAM BW=100MHz Channel=656000 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_64QAM BW=100MHz Channel=656000 RB=270@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_64QAM BW=100MHz Channel=662000 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_64QAM BW=100MHz Channel=662000 RB=270@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_64QAM BW=10MHz Channel=647000 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_64QAM BW=10MHz Channel=647000 RB=24@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_64QAM BW=10MHz Channel=656000 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_64QAM BW=10MHz Channel=656000 RB=24@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_64QAM BW=10MHz Channel=665000 RB=1@0



SA\PC2\NR n77(3700-3980) SCS=30kHz DFT_64QAM BW=10MHz Channel=665000 RB=24@0

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.