



4284 Carneros Way - Jackson, WI 53037 - 262-330-9244

Friday, April 12, 2024

Federal Communications Commission
Authorization and Evaluation Division
1435 Oakland Mills Road
Columbia, MD 21046

SUBJECT: FCC ID: 2AUWRSS-0001, IC: 25652-SS0001, Request for Dismissal

To Whom It May Concern:

We, the undersigned, hereby request through our authorized agent TIMCO, dismissal of FCC ID: 2AUWRSS-0001, IC: 25652-SS0001.

Explanation For the Dismissal Request

During an audit of a production sample requested by TIMCO, the audit failed. It was later determined that the original unit used for testing and awarding of FCC ID: 2AUWRSS-0001, IC: 25652-SS0001 had a defective resistor on it. This was found after comparing the audit unit to the original unit. To prove this was the issue, on another new sample production unit, the resistor was updated to compensate for the resistance of the defective resistor and the unit passed.

Because of this, we are requesting dismissal of the FCC ID and ISED number:

FCC ID: 2AUWRSS-0001
IC: 25652-SS0001

No devices have been marketed or sold with this FCC ID or ISED number in the United States, Canada or anywhere in the world.

Regards,

A handwritten signature in blue ink that reads 'Andrew J. Wanie'.

Andrew J. Wanie

President

AJIE Superior Solutions, LLC