

Authorization Letter

To: Shenzhen LCS Compliance Testing Laboratory Ltd.

Room 101, 201, Building A and Room 301, Building C, Juji Industrial Park,
Yabianxueziwei, Shajing Street, Bao' an District, Shenzhen, Guangdong,
China



Date: **2026-06-16**




We << ALOYS INC.>> authorise the co-approval and use of the documents including test reports used in gaining certification of << 6XD-TC233270 , DSS-TC629328 , DTS-TC374729 , NII-TC679639 >> modify the report. Increase series model

Reference: Original Certificate: 6XD-TC233270 , DSS-TC629328 , DTS-TC374729 , NII-TC679639

Reference: Original report number: LCSA05155084EA, LCSA05155084EB, LCSA05155084EC, LCSA05155084ED, LCSA05155084EE, LCSA05155084EF, LCSA05155084EG, LCSA05155084EH, LCSA05155084EI.

The product is identical to the original supplied for certification except for:

Item of change	
The applicant and manufacturer address have been changed, and add additional model Z12 Ultra SE and add external photos. The difference between Z12 Ultra SE and Z12 Ultra is the difference in DDR, Replace a memory storage chip(DDR), the original model: K4AAG165WA-BCWE change to model: H9HCNNNBKUMLXR-NEE This memory storage chip(DDR) replacement will not affect the RF module and the RF radio frequency power, RF circuit and PCB board did not change, RF data did not change. Update memory storage chip(DDR) product photos, other no changes.	
Before change	After the change
memory storage chip(DDR) product photos: 	memory storage chip(DDR) product photos: 

	
Model: Z12 Ultra	Models.: Z12 Ultra , Z12 Ultra SE
Applicant address and manufacturer address: 6F, 4-5, Yanghyeon-ro 405beon-gil, Jungwon-gu, Seongnam-si, Gyeonggi-do, Republic of Korea	Applicant address and manufacturer address:11F, 31, Hwangsaoul-ro 258beon-gil, Bundang-gu, Seongnam-si, Gyeonggi-do, Republic of Korea
External Photos: 	External Photos: 
Trade Mark: Formuler	Trade Mark: FORMULER

Taking all of the above into consideration, Change in the reporting report number:

LCSA04176002EA, LCSA04176002EB, LCSA04176002EC, LCSA04176002ED, LCSA04176002EE, LCSA04176002EF, LCSA04176002EG, LCSA04176002EH, LCSA04176002EI

Sincerely,

Signature		Date	2026-06-16
Printed Name Company	Regulatory Team ALOYS INC.	Job Title Address	Regulatory Team 11F, 31, Hwangsaoul-ro 258beon-gil, Bundang-gu, Seongnam-si, Gyeonggi-do, Republic of Korea toby@alloys.co.kr
Phone	+82 70 8680 5015	Email	