


FCC/ISED Setup Photos


Revision	Report Date	Reason for Revision
Ø	08/15/2021	Initial Issue.




CEV Setup




OTA Setup 1




OTA Setup 2



REE 30MHz - 1GHz Setup



RSE Above 1GHz Setup



RSE Substitution Method Setup